

Release Notes

Product Name: VS-44H2A

Current Version:

Type	Number	Date
Firmware	1.11	November 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: November 29, 2018

Reference: 13074

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-44H2A	NA	NA	NA

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: VS-44H2A

Current Version:

Type	Number	Date
Firmware	1.11	November 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: November 29, 2018

Reference: 13074

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VS-44H2A

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
12635, 12654	Minor web pages issues.
12664	K-Upload application FW upgrade may end with an error message, even though the upgrade completed successfully.
12675	Device allows 2 simultaneous TCP connections.
12687	No Protocol 3000 report for connected/disconnected SINK. DISPLAY? command response does not indicate valid EDID.
12691	Protocol echo through UDP requires one time access in order to initialize.
12695, 12696	WEB compatibility limitations with iOS Safari browser. Save/upload configuration, FW upgrade and EDID files upload are not supported by iOS.
13300	Product is not reachable using DNS device name via PING command or via the internet URL.
13484	During FW upgrade, switching and network communication do not function.
13823	Protocol 3000 command SW-TIMEOUT response is randomly duplicated.
14672, 14673	Following Factory Default operation through the web page ('Soft Reset' button) the IP settings are kept, but these settings may be displayed incorrectly after the reset. To show the correct IP settings, use 'page refresh' (F5) to show the correct IP settings following the
14674	Factory Default operation through the web page ('Soft Reset' button) may sometimes cause the web page to become unresponsive. Workaround: Close the tab, reopen it and retry.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com