

Release Notes

Product Name: EDID Designer Software

Current Version:

Type	Number	Date
Firmware	–	–
Software	4.6.11.0	May 2019
Web	–	–
Hardware	–	–

RN Date: May 2019

Reference: 15134

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
EDID Designer Software	Any	Yes	Yes

Technical Notes:

- Overview of changes.
- New features are described in the updated User Manual.

Codependency with Other Products and Software:

Product Name	Comments
	See list of supported device on page 4 .

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: EDID Designer Software

Current Version:

Type	Number	Date
Firmware	–	–
Software	4.6.11.0	May 2019
Web	–	–
Hardware	–	–

RN Date: May 2019

Reference: 15134

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed adapters automatic update.
2373	Uninstalling the app while it is still running allows the user to use it normally

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
515	Deleting a currently working EDID file causes unexpected behavior
517	Right click on a local EDID file and trying to delete it can crash application
601	Application crashes when dragging monitor EDID to input area (ability to drag and drop monitor EDID when 'monitor refresh button isn't finished)
1451	Application crashes when moving between Advanced and Simplified tabs
1452	Simplified --> Video - Detailed Timings - Import button and label are moved left when the configuration list is open
1653	When the app is running, not all available com ports are recognized
2364	The string: 'A0123456789' (including the apostrophes), becomes ?A0123456789? when pasted into fields in Descriptor #3
2365	No license agreement shown when installing the EDID Designer
2371	Skipping a SW update causes the upgrade message to stop appearing
4479	Input- EDID change notification implementation
4593	Application crashes when working with Linux based WP-5VH2.
4596	Pop-up doesn't move when the application window is resized
4669	Unable to get the in/out EDID after the HW reset process while connected via ETH port
4670	Application crashes when refreshing the IN - OUT EDID process after device is powered OFF and ON via RS-232
4691	No info regarding connected port



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

QC ID	Deferred Bug Description
4871	Application crashed while connecting to VS-62D/62H devices
4914	Disabling read-only EDID file prevents scrolling
5340	Application crashed when parsing specific EDID

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
2390	In CEA extensions > Audio extension block, the 'Max bit rate' field is not colored when entering a non-valid value
4666	EDID Designer cannot open EDID file
6669	When you copy default EDID by EDID designer the Ext EDID LED is on and not default on VM-214DT

Preceding Version: SW – 4.6.2.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer

Current Version:

Type	Number	Date
Firmware	-	
Software	4.6.2.0	May 2017
Web	-	
Hardware	-	

RN Date: May 2017 (Ver. 5)

Reference: 11206

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
EDID Designer	Any	Yes	N/A

Technical Notes:

- New digital signature algorithm.

Supports the Following Devices:

Product Names		
691	VM-214DT	VS-44HN
692	VM-2DT	VS-62D
DIP-20	VM-2UHD	VS-62DT
DIP-30	VM-3UHD	VS-62H
DIP-31	VM-4HDT	VS-62HA
DIP-31M	VM-4UHD	VS-88HFS
PT-2C	VM-8HN	VS-88HN
TP-578H	VP-31KSI	VS-211UHD
TP-578HDCP	VP-81KSI	VS-411UHD
TP-588D	VS-42HDCP	VS-611DT
TP-590RXR	VS-42HN	WP-20
TP-590TXR	VS-42UHD	WP-577VH
VM-212DT	VS-44HDCP	WP-5VH2
VS-88UT	VS-41H2	VM-218DT
VM-3DT	VM-4DT	VM-2D
TP-580RA		



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer

Current Version:

Type	Number	Date
Firmware	-	
Software	V4.6.2.0	May 2017
Web	-	
Hardware	-	

RN Date: May 2017 (Ver. 4)

Reference: 11206

The following changes were made in this version:

New Features:

	New Feature Description
	New digital signature algorithm

Bugs to Fix in Future Version:

QC ID	Fixed Bug Description
515	Deleting a currently working EDID file causes unexpected behavior
517	Right click on a local EDID file and trying to delete it can crash application
601	Application crashes when dragging monitor EDID to input area (ability to drag and drop monitor EDID when 'monitor refresh button isn't finished)
1451	Application crashes when moving between Advanced and Simplified tabs
1452	Simplified --> Video - Detailed Timings - Import button and label are moved left when the configuration list is open
1653	When the app is running, not all available com ports are recognized
2364	The string: 'A0123456789' (including the apostrophes), becomes ?A0123456789? when pasted into fields in Descriptor #3
2365	No license agreement shown when installing the EDID Designer
2371	Skipping a SW update causes the upgrade message to stop appearing
2373	Uninstalling the app while it is still running allows the user to use it normally
4479	Input- EDID change notification implementation
4593	Application crashes when working with Linux based WP-5VH2.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

QC ID	Fixed Bug Description
4596	Pop-up doesn't move when the application window is resized
4669	Unable to get the in/out EDID after the HW reset process while connected via ETH port
4670	Application crashes when refreshing the IN - OUT EDID process after device is powered OFF and ON via RS-232
4691	No info regarding connected port
4871	Application crashed while connecting to VS-62D/62H devices
4914	Disabling read-only EDID file prevents scrolling
5340	Application crashed when parsing specific EDID

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
2390	In CEA extensions > Audio extension block, the 'Max bit rate' field is not colored when entering a non-valid value
4666	EDID Designer cannot open EDID file
6669	When you copy default EDID by EDID designer the Ext EDID LED is on and not default on VM-214DT

Preceding Version: S – 4.5.0.97



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer
Current Version: S – 4.5.0.97
Version Date: July 2016 (ver.2)
Reference: 9013

Release Type:

Firmware Software Hardware New Product

Technical Notes:

- Multiple bugs were fixed.
- **Note:** When installing this new version, you must de-install the previous version of EDID Designer before performing the new installation.
- If the new installation is not successful, see the installation procedure workaround at the end of this release note.

Supports the Following Devices:

Product Names		
DIP-20	VM-2UHD	VS-44HDCP
DIP-30	VM-3UHD	VS-44HN
PT-2C	VM-4HDT	VS-62D
TP-578H	VM-4UHD	VS-62H
TP-578HDCP	VM-8HN	VS-62HA
TP-588D	VP-31KSI	VS-88HFS
TP-590RXR	VP-81KSI	VS-88HN
TP-590TXR	VS-42HDCP	WP-20
VM-212DT	VS-42HN	WP-577VH
VM-214DT	VS-42UHD	WP-5VH2



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer

Current Version: S – 4.5.0.97

Version Date: July 2016 (ver.2)

Reference: 9013

The following changes were made in this version:

Bug Fixes:

- Various Ethernet and serial connection problems to Kramer devices were fixed.
- The auto update process was fixed.
- Empty file folder copy crashes were fixed.
- “Discard” did not work after removing extension blocks.
- Powering off and on the connected device caused problems when trying to copy the EDID.
- Default EDID problems were fixed.
- Deep color and audio tags remained after the extension information block was erased.
- Device support problems were fixed.
- Several minor bugs were fixed.

Known Issues:

- There is no backward compatibility to the VA-2H.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Installation Procedure Workaround:

- In case of a faulty installation, there is a known Microsoft hotfix (not always applied to all systems) as described here:
<https://support.microsoft.com/en-us/kb/2675806?wa=wsignin1.0>
- The following procedure, recommended by Microsoft, can fix a faulty installation:

<https://social.msdn.microsoft.com/Forums/windows/en-us/365f8c65-b413-428e-af93-f150059a185f/cannot-runinstalluninstall-a-clickonce-application>

- Try to delete the ClickOnce cache folder and install the .net application again. If the OS is Windows 7, the folder should be:
users\[username]\appdata\local\apps\2.0
- Remove the ClickOnce application manually.
- Delete the shortcuts of the ClickOnce application.
- Try to install again (run setup.exe)
- After manually removing the ClickOnce application, try to install it again.

Preceding Version: 1.0.0.79



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer

Preceding Version: S – 1.0.0.79

Version Date: June 2014

Reference: 7254

The following changes were made in this version:

Known Issues:

- There is no backward compatibility to the VA-2H.
- “Discard” doesn’t work when removing extension blocks.
- Powering off and on the connected device may cause problems when trying to copy the EDID after the device is on.
To solve the problem, disconnect and reconnect the device.

Preceding Version: 1.0.0.53



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: EDID Designer

Preceding Version: 1.0.0.53

Version Date: April 2012

Reference: 2236

The following changes were made in this version:

Fixes:

- A failure to save the EDID from download or pressing the save button was fixed.
- An Open Monitor EDID error in Windows 7 was fixed.
- A program crash when trying to read an EDID from a non-existing port was fixed.

Known Issues:

- There are no known issues.

Preceding Version: 1.0.0.43



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Software Name: EDID Designer

Preceding Version: 1.0.0.43

Version Date: September 2011

The following changes were made in this version:

Added Features:

- Support for the VA-2H was added.

Fixes:

- The status row now displays the current status.
- The "Command" menu is disabled when the status is "Disconnected".
- When illegal data is entered in numeric fields an error message is displayed.
- "Save EDID", "Save EDID as" and "Download to" were fixed to work properly.

Known Issues:

There are no known issues.

Preceding Version: 1.0.0.32



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com