

Release Notes

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | 1.0.5 | December 2023 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 24, 2023

Reference: 19004

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| KDS-7-MNGR | Any | Yes | Yes |

Summary:

- Added new feature(s).
- Fixed bugs.

Codependency with Other Products and Software:

| Product Name | Comments |
|--------------|-----------------------------------|
| KDS-EN7 | For new features: Firmware 1.0.10 |
| KDS-DEC7 | For new features: Firmware 1.0.13 |

- There is no codependency with other products or software.

New Features:

| ID | New Feature Description |
|---------------------|---|
| | Support for new features in KDS-EN7 FW 1.0.10 and KDS-DEC7 FW 1.0.13. |
| GB-1071, GB-1073 | Added daylight saving time with start/end date range configuration using Network Time Protocol (NTP). |
| GB-1064 | Added the 802.1X status to the Web-UI. |
| GB-997 | Added encoder channel ID conflict detection and warning. |
| GB-1002 | New UI support for configuring Dante network for KDS-SW3-EN7. |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | 1.0.5 | December 2023 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 24, 2023

Reference: 19004

Bugs Fixed:

| ID | Fixed Bug Description |
|---------|--|
| GB-1046 | Removed 'v' before the version number on LCD, Web-UI, API. |

Preceding Version: 0.7.6



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | 0.7.6 | December 2022 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 26, 2022

Reference: 18526

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| KDS-7-MNGR | Any | Yes | Yes |

Summary:

- Fixed bugs.
- Added features.

Codependency with Other Products and Software:

| Product Name | Comments |
|--------------|----------|
| | |

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | 0.7.6 | December 2022 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 26, 2022

Reference: 18526

New Features:

| | New Feature Description |
|---|---|
| 1 | IE browser is no longer supported. |
| 2 | #TEST-MOD, #FCT-MAC and #FCT-SN commands are supported. |
| 3 | #ADDUSER and #RMUSER API added. |
| 4 | HDMI UI with Home, Refresh, Forward and Back buttons was added. |
| 5 | Editing of group names is supported. |

Modifications:

| | Modification Description |
|---|--|
| 1 | Video Wall Routing Page operation Improved. |
| 2 | The HDMI background image is the Kramer Logo. |
| 3 | UI improvements, such as an active/inactive button, etc. |
| 4 | Password security improved – a strong password is required when user changes password. |
| 5 | Default IP is now 192.168.1.39 |

Bugs Fixed:

| ID | Fixed Bug Description |
|--------|---|
| | Low temperature boot fail issue fixed. |
| | Some TVs could not show the full HDMI UI – this issue is now fixed. |
| | Fixed the issue that Video Wall Routing page changes the IR/CEC/RS232 routing too. |
| GB-988 | When importing a configuration file, the device changed according to the configuration file and not on the selection set by the menu. |
| GB-987 | Import feature did not work properly when security was set to on. |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

| ID | Fixed Bug Description |
|------------------|---|
| GB-973 | In the security page, the radio button was active till the end of the line but selection was not carried out. |
| GB-943 | The manager did not scan the network for changes automatically (only following refresh). |
| GB-902 | Presets did not indicate which preset is active. |
| GB-844 GB-843 | Import / export system files did not work properly. |
| GB-812 | Heat Level temperature status displays an incorrect character for the Celsius degree. Should be "40". |
| GB-806 | LCD menu page doesn't return to main page after exceeding the time out period. |

Bugs to Fix in Future Versions:

| ID | Deferred Bug Description |
|--------|---|
| GB-842 | When trying to switch 2 encoders TO 1 decoder in Icon routing View from the HDMI output, the UUT performs reset in HDMI OUTPUT. |

Known Limitations (including compatibility limitations):

| ID | Limitation Description |
|----|------------------------|
| | |

Preceding Version: 0.5.4



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|-----------|
| Firmware | 0.5.4 | June 2022 |
| Software | – | – |
| Web | – | – |
| Hardware | | |

RN Date: July 3, 2022

Reference: 60-000790

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| KDS-7-MNGR | | | |

IMPORTANT: If you have a device with FW version lower than 0.5.4 (beta units), please consult with the Kramer Support Team for special FW update instructions.

Summary:

This is a release note for a new product. To view the product's webpage, see:

<https://www.kramerav.com/il/product/KDS-7-MNGR>

Codependency with Other Products and Software:

There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KDS-7-MNGR

Current Version:

| Type | Number | Date |
|----------|--------|-----------|
| Firmware | 0.5.4 | June 2022 |
| Software | – | – |
| Web | – | – |
| Hardware | | |

RN Date: July 3, 2022

Reference: 60-000790

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| KDS-7-MNGR | | Y | |

IMPORTANT: If you have a device with FW version less than 0.5.4 (beta units), please consult with the Kramer Support Team for special FW update instructions.

Summary:

This is a release note for a new product. To view the product's webpage, see:

<https://www.kramerav.com/il/product/KDS-7-MNGR>

Codependency with Other Products and Software:

There is no codependency with other products or software.

Open Bugs to Fix in Future Versions:

| ID | Deferred Bug Description |
|-------------------|---|
| GB-844, GB-843 | To import / export system files, you need to select "ALL". |
| GB-841 | KDS-ROUTE? command does not display the encoder device name as expected. |
| GB-831 | #TIME-LOC command does not support all time zones. |
| GB-821 | Need to update the new Kramer address in the About page. |
| GB-812 | Heat Level temperature status displays an incorrect character for the Celsius degree. Should be "40°" |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

| ID | Deferred Bug Description |
|--------|--|
| GB-806 | LCD menu page doesn't return to main page after exceeding the time out period. |
| GB-706 | #NET-IP command works only in UDP protocol. |

Known Limitations (including compatibility limitations):

| ID | Limitation Description |
|----|------------------------|
| | |

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com