

Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65520	June 2024
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	June 20, 2024		
Reference:	019751		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	Any	Yes	Yes

Summary:

• Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65520	June 2024
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	May 20, 2024		
Reference:	019751		

The following changes were made in this version:

Bugs Fixed:

ID	Fixed Bug Description
86324	Noise heard on audio output upon HDMI input connection

Preceding Version: 1.0.65513





Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65513	May 2024
	Software		-
	Web	-	-
	Hardware	03	May 2024
RN Date:	May 20, 2024		
Reference:	019688		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	Any	Yes	Yes

Summary:

• Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65503	May 2024
	Software	_	_
	Web	_	_
	Hardware	03	May 2024
RN Date:	May 20, 2024		
Reference:	019688		

The following changes were made in this version:

Bugs Fixed:

QC ID		Fixed Bug Description
		Potential improper USB-C connection for Lenovo laptop models (Gen2 or later). Workaround: Unplug/re-plug laptop till properly connected
	-	was fixed on HW Revision 03 and higher. To check your device's product revision number, label on the box.

Preceding Version: 1.0.65072





Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65072	January 2024
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	January 1, 2024		
Reference:	19443		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

• There is no codependency with other products or software.

Replaced Products:

N/A





Product Name:	SWT3-31-HU		
Current Version:	Туре	Number	Date
	Firmware	1.0.65072	January 2024
	Software	-	-
	Web	_	_
	Hardware	_	_
RN Date:	January 1, 2024		
Reference:	19443		

The following changes were made in this version:

New Features:

New Feature Description
Configurable LAN connection via USB-C.
Auto EDID-support for 2-channel audio.

Modifications:

N/A

Dropped Features:

N/A

Bugs Fixed:

ID	Fixed Bug Description
2016	Detected buttons click is longer than standard.

Bugs to Fix in Future Versions:

N/A

Known Limitations (including compatibility limitations):

ID	Description
85605	Macbook Pro improper USB-C LAN connection.
	MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver.
	https://www.asix.com.tw/en/product/USBEthernet/High-
	Speed USB Ethernet/AX88772C



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u> Web: <u>www.kramerav.com</u>



Preceding Version: 1.0.64477



KRAMER ELECTRONICS, Ltd. E-mail: info@kramerav.com Web: www.kramerav.com



Release Notes History

Product Name: SWT3-31-HU **Current Version:** Туре Number Date 1.0.64477 October 2023 Firmware Software _ _ Web _ _ Hardware _ _ October 25, 2023

RN Date: Reference:

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	N/A	N/A	N/A

Summary:

• This is a release note for a new product.

Codependency with Other Products and Software:

• There is no codependency with other products or software.

Replaced Products:

• N/A





Release Notes History

Product Name:

SWT3-31-HU

October 25, 2023

Current Version:

Туре	Number	Date		
Firmware	1.0.64477	October 2023		
Software	-	-		
Web	-	-		
Hardware	_	_		

RN Date: Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-31-HU

Issues to Fix in Future Versions:

ID	Deferred Issue Description		
85394	Time location isn't disabled for disabled NTP server.		
	Incorrect P3K time query response.		
	No connection of active host with newly plugged USB device. Workaround: Re-switch active host.		
85256	Web-UI gateway active/inactive option is unsupported.		
85246	Input signal status does not have port numbers near signal name at Web UI.		
85244	Few web-UI configured attributes are not exported/imported.		
84782	After device restart, Web page should be refreshed manually.		
84431	Web-UI color depth is not configurable.		
83357	Long delay on initial web-UI landing page load.		
84573	After device restart, Web page should be refreshed manually.		
84200	No command name edit when contains 2 spaces.		
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.		

Known Limitations (including compatibility limitations):

ID	Limitation Description
83350	Default hostname may contain further truncated model name to comply with its standard-required uniqueness.
85263	Web-UI action command length is up to 300 characters.

Preceding Version: N/A





Release Notes History



KRAMER ELECTRONICS, Ltd. E-mail: info@kramerav.com Web: www.kramerav.com