

Product Name: SWT3-41-U

Current Version: Type

| Туре | Number | Date |
|----------|-----------|----------|
| Firmware | 1.0.65487 | May 2024 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | 04 | May 2024 |

RN Date: May 20, 2024

Reference: 019689

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------------|---------------------------|---|
| SWT3-41-U | Any | Yes | Yes |

Summary:

Fixed a bug.

Codependency with Other Products and Software:

There is no codependency with other products or software.



Product Name: SWT3-41-U

Current Version: Type Number Date

Firmware 1.0.65487 May 2024

Software – –

Web – –

Hardware 04 May 2024

RN Date: May 20, 2024

Reference: 019689

The following changes were made in this version:

Bugs Fixed:

| QC ID | Fixed Bug Description |
|-------|---|
| | Potential improper USB-C connection for Lenovo laptop models (Gen2 or later). Workaround: Unplug/re-plug laptop till properly connected |
| | was fixed on HW Revision 04 and higher. To check your device's product revision number, alabel on the box. |

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 1838 | Control gateway is supported for TCP clients only. |

Preceding Version: 1.0.65098

E-mail: info@kramerav.com
Web: www.kramerav.com



Product Name: SWT3-41-U

Current Version: Type

| Туре | Number | Date |
|----------|-----------|--------------|
| Firmware | 1.0.65098 | January 2024 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: January 1, 2024

Reference: 19456

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------------|---------------------------|---|
| SWT3-41-U | Any | Yes | Yes |



FW 1.0.65098 is only relevant for product revision 0101. To check your device's product revision number, check the label on the box.

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

• There is no codependency with other products or software.

Replaced Products:

N/A



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>



Product Name: SWT3-41-U

Current Version: Type

| Туре | Number | Date |
|----------|-----------|--------------|
| Firmware | 1.0.65098 | January 2024 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: January 1, 2024

Reference: 19456

The following changes were made in this version:

New Features:

| New Feature Description |
|--|
| Configurable LAN connection via USB-C. |

Modifications:

| QC ID | Modification Description |
|-------|--|
| | Better stabilization of USB -C connection. |

Dropped Features:

N/A

Bugs Fixed:

| QC ID | Fixed Bug Description |
|-------|---|
| 2076 | Stability of USB device connection. |
| 2071 | Detected buttons click is longer than standard. |

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 1838 | Control gateway is supported for TCP clients only. |
| | Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source. |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com



Known Limitations (including compatibility limitations):

| ID | Description |
|-------|---|
| 85605 | Macbook Pro improper USB-C LAN connection. |
| | MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver. |
| | https://www.asix.com.tw/en/product/USBEthernet/High- |
| | Speed USB Ethernet/AX88772C |

Preceding Version: V1.0.64879



Release Notes History

Product Name: SWT3-41-U

Current Version: Type

| Туре | Number | Date |
|----------|------------|---------------|
| Firmware | V1.0.64879 | November 2023 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: November 30, 2023

Reference:

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------------|---------------------------|---|
| | Opgrado | | rtoquirou |

Summary:

This is a release note for a new product.

Codependency with Other Products and Software:

• There is no codependency with other products or software.

Replaced Products:

N/A

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>



Release Notes History

Product Name: SWT3-41-U-T

Current Version: Type

| Туре | Number | Date |
|----------|------------|---------------|
| Firmware | V1.0.64879 | November 2023 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: November 30, 2023

Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-41-U-T

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 1838 | Control gateway is supported for TCP clients only. |
| | Detected buttons click is longer than standard. |
| | Rarely, especially post power-cycle, plugged USB-C source is undetected. |
| | Workaround: Unplug & re-plug source. |

Known Limitations (including compatibility limitations): N/A

Preceding Version: N/A