

## Release Notes

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:**

Type	Number	Date
Firmware	1.13.62782	August 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** August 16, 2023

**Reference:** 19103

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-590TXR, TP-590RXR	Any	Yes	Yes

### Summary:

- Updated brand



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:**

Type	Number	Date
Firmware	1.13.62782	August 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** August 16, 2023

**Reference:** 19103

### Modifications:

QC ID	Modification Description
	FW includes updated logo

**Preceding Version:** 7.5.7



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:**

Type	Number	Date
Firmware	7.5.7	June 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 24, 2021

**Reference:** 17509

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-590TXR, TP-590RXR	Any	Yes	Yes

### Technical Notes:

- Fixed bugs.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:**

Type	Number	Date
Firmware	7.5.7	June 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 24, 2021

**Reference:** 17509

The following changes were made in this version:

### Bugs Fixed:

QC ID	Fixed Bug Description
6580, 18660, 19265	Improved USB camera extension and compatibility support, including support for Logitech Brio and 4K USB cameras.
6596, 17580	Improved Ethernet extension support.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** NP – 1.0



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:** NP – 1.0

**Version Date:** February 2016

**Reference:** 7931

**Release Type:**

Firmware     Software     Hardware     New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-590TXR	N/A	N/A	N/A
TP-590RXR	N/A	N/A	N/A

**Technical Notes:**

- This is a release note for new products.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** TP-590TXR, TP-590RXR

**Current Version:** NP – 1.0

**Version Date:** February 2016

**Reference:** 7931

This is a release note for new products.

### Internal Known Issues:

QC ID	Description
5718	The Output state in TP-590RXR is active although the SINK on output is disconnected
5724	The analog out signal in TP-590RXR with NEC SINK on output disappears because of the copying EDID is wrong
5753	The output RX-590RXR status on web is "DISCONNECTED" although the sink is ON
5824	No HDCP indication on input TP-590RXR
5836	The output status in TP-590Rxx is disconnected after reset device via tera term ,the audio and video signal on output is well
6131	HDCP problem when using webpage sometimes

### Known Issues:

- There may be problems saving the configuration.
- When upgrading the Valens chipset, the upload may sometimes fail. To recover, cycle the power and try the upload again.
- Sometimes on the Web page the output is shown as “disconnected” while it is still connected. To recover, refresh the Web page.
- For some models of NEC displays/projectors there may be no audio.  
Workaround: edit the EDID as follows:
- Change the revision number in the NEC EDID block from 1 to 3.
- Add the specific vendor in NEC EDID Block 1.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)