

## **Release Notes**

Product Name: VP-427X1

Current Version: Type

| Туре     | Number | Date           |
|----------|--------|----------------|
| Firmware | 1.05   | September 2022 |
| Software | _      | _              |
| Web      | _      | _              |
| Hardware | _      | _              |

RN Date: September 15, 2022

Reference: 17967

#### **Kramer Product Affected:**

| Product Name | Minimum FW<br>Version for<br>Upgrade | Recommended for All Units | Only if Added<br>Features are<br>Required |
|--------------|--------------------------------------|---------------------------|---|
| VP-427X1     | Any                                  | Yes                       | Yes                                       |

### Summary:

• Fixed bugs.

## **Codependency with Other Products and Software:**

| Product Name | Comments |
|--------------|----------|
|              |          |

• There is no codependency with other products or software.



## **Release Notes**

Product Name: VP-427X1

Current Version: Type

| Туре     | Number | Date           |
|----------|--------|----------------|
| Firmware | 1.05   | September 2022 |
| Software | _      | _              |
| Web      | _      | _              |
| Hardware | _      | _              |

RN Date: September 15, 2022

Reference: 17967

## **Bugs Fixed:**

| QC ID | Fixed Bug Description   |
|-------|---|
| 62846 | Default UDP port 50000 does not listen to broadcast.                                    |
| 79824 | Typo in the popup after changing an input's name – it says "seccuss" instead of success |
| 79812 | Icon shows that the machine is ON after WEB login                                       |
| 19226 | The current consumption in standby mode is almost identical to that in normal operation |
|       | mode. Is it possible to shut down more of the electronics when in standby?              |
| 19465 | When the Toggle pin is shorted to GND and the TOGGLE PIN is defined as INPUT SELECT,    |
|       | pressing any front-panel button results in switching the input                          |

## **Known Limitations (including compatibility limitations):**

| QC ID | Limitation Description |
|-------|------------------------|
|       | None listed            |

**Preceding Version**: 1.04



# **Release Notes History**

Product Name: VP-427X1

Current Version: Type

| Type     | Number | Date         |
|----------|--------|--------------|
| Firmware | 1.04   | October 2021 |
| Software | _      | _            |
| Web      | _      | _            |
| Hardware | _      | _            |

RN Date: October 21, 2021

Reference: 08508

#### **Kramer Product Affected:**

| Product Name | Minimum FW<br>Version for<br>Upgrade | Recommended for All Units | Only if Added<br>Features are<br>Required |
|--------------|--------------------------------------|---------------------------|---|
| VP-427X1     | N/A                                  | N/A                       | N/A                                       |

### Summary:

This is a release note for a new product.

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.



# **Release Notes History**

Product Name: VP-427X1

Current Version: Type

| Type     | Number | Date         |
|----------|--------|--------------|
| Firmware | 1.04   | October 2021 |
| Software | _      | _            |
| Web      | _      | _            |
| Hardware | _      | _            |

RN Date: October 21, 2021

Reference: 08508

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VP-427X1

### **Bugs to Fix in Future Versions:**

| QC ID | Deferred Bug Description |
|-------|--------------------------|
|       | None listed              |

### **Known Limitations (including compatibility limitations):**

| QC ID | Limitation Description |
|-------|------------------------|
|       | None listed            |

Preceding Version: N/A