

Release Notes

Product Name: Product

Current Version: Type

Туре	Number	Date
Firmware	01.01.65338	March 2024
Software	ı	_
Web	ı	_
Hardware	_	_

RN Date: March 10, 2024

Reference: 19584

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Product	N/A	N/A	N/A

Summary:

Bug Fixes

Codependency with Other Products and Software:

• There is no codependency with other products or software.



Release Notes

Product Name: Product

Current Version:TypeNumberDateFirmware01.01.65338March 2024

 Firmware
 01.01.65338
 March 2024

 Software

 Web

 Hardware

RN Date: March 10, 2024

Reference: 19584

The following changes were made in this version:

Bugs Fixed:

ID	Fixed Bug Description
85933	Clean display view for 1024x768 resolution
2434, 2433, 2431	Improved multi-view display with various related issues fixing
2199	Setting specific IP address issues fixed.
2200	Fix LAN operation stability.

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
80800	Embedded Audio - When an output is set to off, the embedded audio stream is not muted.
80809	Output Resolution - Does not differentiate between 1360x768 and 1366x768 output resolutions.

Known Limitations (including compatibility limitations):

ID	Limitation Description	
	None listed	

Preceding Version: V1.1.9481



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com



Release Notes History

Product Name: Product

Current Version: Type Number Date

Type	Number	Date
Firmware	01.01.65301	January 2024
Software	-	_
Web	_	_
Hardware	_	_

RN Date: February 24, 2024

Reference: 19481

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Product	N/A	N/A	N/A

Modifications:

ID	Improvements
2398, 2337, 2335	Improper support of AUD-SIG-TYPE, Aud_mute? & vmute? commands
81131, 2199	Impropper DNS (hostname) & specific IP address setting
2247	Factory Reset button robust operation improvement
2299	Front panel ALL switching causes no output signal on switched port
2200, 2391	Device operation rarely freeze, unfreezing only via a power cycle
82899	Device crash on preset recall

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
80800	Embedded Audio - When an output is set to off, the embedded audio stream is not muted.
80809	Output Resolution - Does not differentiate between 1360x768 and 1366x768 output resolutions.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>



Release Notes History

Known Limitations (including compatibility limitations):

ID	Limitation Description
2303	Since changing the status of HDCP ON INPUTS from ON to OFF does not trigger HPD, if a source is already connected, it may be necessary to disconnect and then reconnect it.

Preceding Version: V1.1.62740



Release Notes History

Product Name: Product

Current Version: Type Number Date

- <i>J</i>		= 0.10
Firmware	V1.1.62740	March 2022
Software	_	_
Web	_	_
Hardware	_	_

RN Date: March 21, 2022 **Reference:** 20-80552030

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
Product	N/A	N/A	N/A

Summary:

This is a release note for a new product. For a list of new product features see:

https://www.kramerav.com/product/vsm-404netxl

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
80800	Embedded Audio - When an output is set to off, the embedded audio stream is not muted.
80809	Output Resolution - Does not differentiate between 1360x768 and 1366x768 output resolutions.

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com