

## Release Note

**Product Name:** VP-773A

<b>Current Version:</b>	<b>Ver.Type</b>	<b>Ver No.</b>	<b>Date</b>
	<b>Firmware</b>	1.0.0.39389 34.52.52.42920	October 2017
	<b>Software</b>	–	–
	<b>Web</b>	–	–
	<b>Hardware</b>	–	–

**RN Date:** October 2017

**Reference:** 12728

### Kramer Product Affected:

<b>Product Name</b>	<b>Minimum FW Version for Upgrade</b>	<b>Recommended for All Units</b>	<b>Only if Added Features are Required</b>
VP-773A	Any	Yes	N/A

### Technical Notes:

- New features were added to the web pages.
- Fixed various bugs.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note

**Product Name:** VP-773A

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.0.0.39389 34.52.52.42920	October 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 2017

**Reference:** 12728

The following changes were made in this version:

### New Features:

	New Feature Description
	Panel Lock – added to webpage, select one of the three states: Off (panel buttons are unlocked) / All (all panel buttons are locked) / Menu only (only the MENU button is locked)
	Lock Save – click ON to save the lock panel lock state after a system reboot

### Bugs Fixed:

QC ID	Fixed Bug Description
	Bottom pixel no longer missing when the input resolution is equal to output resolution
6876	Audio no longer pops when switching between HDMI and VGA + audio or Display port & VGA + audio
10753	Fixed load saved configuration issue
	Reply from firmware to “lock-fp?” and “lock-fp-save?” was returned with question mark
	Restricted PIP size on 1080p@23.976/24/25/29.97/30 resolutions to max size of 960x540, on other resolutions restricted PIP max width of 1600

**Preceding Version:** F – 34.52.52.23495.23112.P



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VP-773, VP-773A  
**Current Version:** F – 34.52.52.23495.23112.P  
**Version Date:** November 2015  
**Reference:** 9321

**Release Type:**

Firmware       Software       Hardware       New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-773A	Any	Yes	N/A

**Technical Notes:**

- Extensive changes and fixes were made to the device and Web firmware.
- New features are explained in detail in the updated version of the user manual.
- This is the formal version of the firmware that was released as a hotfix 33.50.51.21106.21107.P in July 2015.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VP-773, VP-773A  
**Current Version:** F – 34.52.52.23495.23112.P  
**Version Date:** November 2015  
**Reference:** 9321

The following changes were made in this version:

### Added Features:

- Input EDID selections were added: Multiple/Single Modeline.
- Two factory reset options were added: Including ETH, Excluding ETH.
- Three auto switching modes were added: Off, Scan, Last connected.
- Three image shift modes were added: Auto, Semi Auto, Customized.
- A P3000 command “AUD-RESET” was added that resets the audio system.
- An Analog Noise Filter was added to determine the analog audio input threshold.
- Multiple sockets for control ports (5000, 50000) and the tunneling port were added allowing control from multiple computers.
- Fade-through-black speed can be set.

### Fixes:

- Significant anti-audio loss measures were added to prevent audio loss problems.
- Video – When switching between HDCP and non HDCP sources sometimes there was HDCP snow or no output signal.
- Video – There was image tearing for output resolutions 1080p23.97/24/25/29.97/30.
- Web COMM – Preset configuration recall was inconsistent.
- Web COMM – There were problems with FW upgrading via the Web page.
- OSD – There was incorrect PIP HDCP presentation at the device info menu.
- OSD – The IP data in OSD information did not update.
- Flash memory – Did not save protocol settings properly.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

- Improved robustness of handling multiple and contiguous P3K commands and port tunneling using scripts.
- Mic audio was interrupted by switching.
- Miscellaneous OSD and web GUI bug fixes.
- Fixed some front-panel keyboard bugs.
- Fixed bugs in TP data tunneling.
- Fixed issue of lost EDID on powering up the unit.
- Protocol command improvements and fixes.
- Corrected problems with auto-sync off feature.
- Inconsistencies between OSD and webpages.
- Fixed miscellaneous IP and comm issues.
- Miscellaneous audio fixes and enhancements.
- Browser related fixes.
- Fixed some HDCP compliance issues.
- Fixed issues related to firmware upgrading.
- Fixed issues with Mac inputs.
- Fixed issues with specific input and output video resolutions.
- Fixed some video enhancement and picture handling issues.
- Fixed issues with blank and freeze.
- Corrected color space issues.
- Miscellaneous bug fixes and enhancements.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

The following **Web related** changes were made in this version:

### Added Features:

- Auto switching was added.
- Added new fields and options to the emergency alert system.
- Input settings were added.
  - Overscan combo-box
  - EDID-mode combo-box
  - Image shift mode
- Two types of factory reset were added.
- The "Analog Noise Filter" function was added.
- Global additions:
  - Full screen icon (top right corner)
  - Dialog for changing protocol to P3K (when the protocol was legacy)
  - Significant Web page communication improvement
  - Significant Web page communication improvement on mobile devices
  - Web page can now be accessed from MAC computers

### Fixes:

- Emergency Alert System (EAS) message bugs were fixed.
- Take mode, Zoom and PIP, and windows' customization were improved.
- Input settings slider and communication were improved.
- The audio slider was improved.
- Save/load configuration: bugs were fixed, and new commands were added to the configuration file.

### Known Issues:

- Firmware upgrade is not supported on mobile devices (iPad, Galaxy Note, etc.)
- Firmware upgrade is not supported on MAC computers

**Preceding Version:** F –34.50.51.21106.21107.P (hotfix)



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VP-773, VP-773AMP  
**Preceding Version:** F –34.50.51.21106.21107.P (hotfix)  
**Version Date:** July 2014  
**Reference:** 9991

The following changes were made in this version:

### Fixes:

- Output resolution 1280x800@60 was fixed.
- EAS message layout was fixed.

### Known Issues:

- There are no known issues.

**Preceding Version:** F – 34.35.47.15263.15185.P (beta)



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VP-773, VP-773AMP  
**Preceding Version:** F – 34.35.47.15263.15185.P (beta)  
**Version Date:** July 2014  
**Reference:** 9990

The following changes were made in this version:

### Added Features:

Added a full functionality Web page supporting the following browsers:

- Windows7:
  - IE (32/64 bits): version 10
  - Firefox: version 30
  - Chrome: version 35
- MAC (PC):
  - Chrome: version 35
  - Firefox: version 27
- Android OS:
  - Chrome: version 35
- iOS:
  - Chrome: version 35
  - Safari (the version depend on IOS version)
- Signal color select was added.
- EAS –minor and moderate severities are used as messages rather than alerts.

**Note:** The Web interface user ID is “admin” and the password is “1234”.

- Web page only, new functions:
  - Mic mute, line mix mute
  - Mic TA hold time
  - Mic TA attack time
  - Mic TA release time
  - Volume pre-limiter



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Note History

### Fixes:

- Web page and firmware bugs were fixed in this version.

### Known Issues:

- There are no known issues.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)