

Release Notes

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.3_000	February 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 28, 2021

Reference: 17248

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-42H2	Any	Yes	Yes

Technical Notes:

- Support for the chipset in the new version of the HW.



This firmware is applicable ONLY to VS-42H2 Revision 01 or higher. Upgrading an incompatible device with this FW can cause the device to be unusable.

Verify which HW Revision of VS-42H2 you own. :

VS-42H2 Revision 01 or higher include a silver sticker next to the serial number marked R: 01 or higher.

Older versions of VS-42H2 do not contain a revision number.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.3_000	February 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 28, 2021

Reference: 17248

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13498	Sometimes, the new audio channel is heard for a short moment during the switching transition.
13656	Some bugs with iOS and Android devices.
14046	In Auto mode – Copying EDID to all inputs causes device to switch the outputs to input #1.
14047	In Auto mode – Changing the HDCP mode of an input causes it to switch between inputs.
14048	Issues with reading EDID for DVI devices.
14235	Sometimes, system fails sometimes to copy EDID from OUT1 to inputs.
15344	Reading EDID using Explorer 11 sometimes causes browser to get stuck.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.2_0000



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.2_0000	April 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 26, 2020

Reference: 16294

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-42H2	Any	Yes	Yes

Technical Notes:

- Fixed a bug.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.2_0000	April 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 26, 2020

Reference: 16294

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
14024	Issue when changing the IP address.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13498	Sometimes, the new audio channel is heard for a short moment during the switching transition.
13656	Some bugs with iOS and Android devices.
14046	In Auto mode – Copying EDID to all inputs causes device to switch the outputs to input #1.
14047	In Auto mode – Changing the HDCP mode of an input causes it to switch between inputs.
14048	Issues with reading EDID for DVI devices.
14235	Sometimes, system fails sometimes to copy EDID from OUT1 to inputs.
15344	Reading EDID using Explorer 11 sometimes causes browser to get stuck.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.1_0001



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.1_0001	May 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 7, 2019

Reference: 13662

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-42H2	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VS-42H2

Current Version:

Type	Number	Date
Firmware	1.1_0001	May 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 7, 2019

Reference: 13662

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VS-42H2

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13498	Sometimes, the new audio channel is heard for a short moment during the switching transition.
	Some bugs with iOS and Android devices.
14046	In Auto mode – Copying EDID to all inputs causes device to switch the outputs to input #1.
14047	In Auto mode – Changing the HDCP mode of an input causes it to switch between inputs.
14048	Issues with reading EDID for DVI devices.
14235	Sometimes, system fails sometimes to copy EDID from OUT1 to inputs.
15344	Reading EDID using Explorer 11 sometimes causes browser to get stuck.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com