

Features are

Required

N/A

Product Name	Minimum FW	Recommended	Only if Added
ramer Product Affected:			
Firmware	Software	☐ Hardware	☐ New Product
Release Type:			
Reference:	8777		
Version Date:	May 2015		
Current Version:	F – 3.3		
Product Name:	VS-44HN		

for All Units

Yes

VS-44HN Any

Technical Notes:

Product Name

• An HDMI audio problem was fixed.

Codependency with Other Products and Software:

Version for

Upgrade

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com $Web: \underline{\ \ www.kramerelectronics.com}$



Product Name: VS-44HN Current Version: F - 3.3

Version Date: May 2015

Reference: 8777

The following changes were made in this version:

Fixes:

• Sometimes after reconnecting the HDMI input there was no audio in the HDMI output signal.

Known Issues:

• There are no known issues.

Preceding Version: F - 3.2



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerel.com</u>
Web: <u>www.kramerelectronics.com</u>



Product Name: VS-44HN **Preceding Version**: F - 3.2

Version Date: October 2014

Reference: 7812

The following changes were made in this version:

Fixes:

- Random DVI video noise with an 840HxI was fixed.
- The model name is set for the device at the first power on.

Known Issues:

There are no known issues.

Preceding Version: F - 3.1



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com



Product Name: VS-44HN

Preceding Version: F - 3.1

Version Date: August 2014

Reference: 7476

The following changes were made in this version:

New Features:

- Fast switching was added.
- An HDCP ON/OFF option was added.

Fixes:

• Various bugs were fixed.

Known Issues:

• There are no known issues.

Preceding Version: F - 2.3



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VS-44HN **Preceding Version**: F - 2.3

Version Date: October 2013

Reference: 6018

The following changes were made in this version:

Fixes:

• A bug in the GEDID command was fixed.

Known Issues:

• There are no known issues.

Preceding Version: F - 2.2



E-mail: info@kramerel.com
Web: www.kramerelectronics.com



Product Name: VS-44HN **Preceding Version**: F - 2.2

Version Date: March 2013

Reference: 5073

The following changes were made in this version:

Added Features:

A Reset command was added for Protocol 2000.

Fixes:

• When storing from the keypad, the device did not send the relevant command to K-Router.

Known Issues:

There are no known issues.

Preceding Version: F - 1.3



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com



Preceding Version: F - 1.3

Version Date: August 2012 (Update)

Reference: 3848

The following changes were made in this version:

Fixes:

- The numbering of the setups under front panel buttons was in the wrong order.
- When one of the outputs was set off K-Router reported that all outputs were off.

Known Issues:

• The IR remote control does not work when the device is set to Protocol 3000. It does work when the device is set to Protocol 2000.

Preceding Firmware Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com