

Product Name:	VS-44HN		
<b>Current Version:</b>	F – 4.0		
Version Date:	June 2016		
Reference:	10660		
Release Type:			
🛛 Firmware	Software	Hardware	New Product

## Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-44HN	Any	Yes	N/A

### **Technical Notes:**

• Audio distortions were fixed.

## **Codependency with Other Products and Software:**

Product Name	Comments

• There is no codependency with other products or software.





Product Name:	VS-44HN
Current Version:	F – 4.0
Version Date:	June 2016
Reference:	10660

The following changes were made in this version:

### Fixes:

• While connecting a VS-311H to a VS-44HN and then switching between sources, the audio distorts.

## Known Issues:

• There are no known issues.

**Preceding Version:** F – 3.3





Product Name:VS-44HNPreceding Version:F - 3.3Version Date:May 2015Reference:8777

The following changes were made in this version:

### Fixes:

• Sometimes after reconnecting the HDMI input there was no audio in the HDMI output signal.

## Known Issues:

• There are no known issues.

**Preceding Version:** F – 3.2





Product Name:VS-44HNPreceding Version:F - 3.2Version Date:October 2014Reference:7812

The following changes were made in this version:

### Fixes:

- Random DVI video noise with an 840HxI was fixed.
- The model name is set for the device at the first power on.

### **Known Issues:**

• There are no known issues.

Preceding Version: F – 3.1





Product Name:VS-44HNPreceding Version:F - 3.1Version Date:August 2014Reference:7476

The following changes were made in this version:

## **New Features:**

- Fast switching was added.
- An HDCP ON/OFF option was added.

### Fixes:

• Various bugs were fixed.

### Known Issues:

• There are no known issues.

**Preceding Version:** F – 2.3





Product Name:VS-44HNPreceding Version:F - 2.3Version Date:October 2013Reference:6018

The following changes were made in this version:

## Fixes:

• A bug in the GEDID command was fixed.

## Known Issues:

• There are no known issues.

**Preceding Version:** F – 2.2





Product Name:VS-44HNPreceding Version:F - 2.2Version Date:March 2013Reference:5073

The following changes were made in this version:

## Added Features:

• A Reset command was added for Protocol 2000.

### Fixes:

• When storing from the keypad, the device did not send the relevant command to K-Router.

### **Known Issues:**

• There are no known issues.

Preceding Version: F - 1.3





Preceding Version:	F - 1.3
Version Date:	August 2012 (Update)
Reference:	3848

The following changes were made in this version:

#### Fixes:

- The numbering of the setups under front panel buttons was in the wrong order.
- When one of the outputs was set off K-Router reported that all outputs were off.

### Known Issues:

• The IR remote control does not work when the device is set to Protocol 3000. It does work when the device is set to Protocol 2000.

## Preceding Firmware Version: N/A

