

## Release Notes

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	2.3_0002 1.2.0	November 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 14, 2021

**Reference:** 17526

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88H2A	Any	Yes	Yes

### Summary:

- Fixed several bugs.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	2.3_0002 1.2.0	November 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 14, 2021

**Reference:** 17526

### Bugs Fixed:

QC ID	Fixed Bug Description
19028	After the ALL button is used for routing, the routing is implemented correctly, but upon the next power cycle, the video routing is not saved, only the audio routing is saved. Workaround: To retain an “ALL” operation routing, even after a power cycle, use the Protocol 3000 command or embedded web page to perform the “ALL” routing.
19464	Video output working properly on all inputs and outputs.
19524	Improved video stability after switching.
19530	Audio now switches simultaneously with video.
19531	Improved switching between DVI and HDMI sources.
19602, 19610	Web pages now work properly.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15437	Auto Switching may occur unexpectedly following EDID copy operation.
17253	When UDP port is changed from the default of 50000, Kramer Network not automatically discover the device.
17275	The API command uses a generic volume span of 0 to 100 and the web UI volume slider uses -50dB to 25dB.
17276	Web Login – When activating 'Authentication' you need to define a new password (default is empty string).
17572	After changing the IP address via the web UI a page refresh is required.
18970	A failed Firmware upgrade due to accidental power shutdown requires system recovery sequence. Please contact Kramer technical support for information.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** 2.1\_0005 1.1.2



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	2.1_0005 1.1.2	April 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** April 18, 2021

**Reference:** 17260

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88H2A	Any	Yes	Yes

### Technical Notes:

- Fixed several bugs.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	2.1_0005 1.1.2	April 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** April 18, 2021

**Reference:** 17260

### Bugs Fixed:

QC ID	Fixed Bug Description
19028	After the ALL button is used for routing, the routing is implemented correctly, but upon the next power cycle, the video routing is not saved, only the audio routing is saved. Workaround: To retain an “ALL” operation routing, even after a power cycle, use the Protocol 3000 command or embedded web page to perform the “ALL” routing.
19185	TCP connection instability with Kramer Control devices.
19291	Sporadic video loss on video outputs.
19229	DGKAT extension (TP-571->TP-572) cascade: instability on output after reconnection.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15437	Auto Switching may occur unexpectedly following EDID copy operation.
17253	When UDP port is changed from the default of 50000, Kramer Network not automatically discover the device.
17275	The API command uses a generic volume span of 0 to 100 and the web UI volume slider uses -50dB to 25dB.
17276	Web Login – When activating 'Authentication' you need to define a new password (default is empty string).
17572	After changing the IP address via the web UI a page refresh is required.
18970	A failed Firmware upgrade due to accidental power shutdown requires system recovery sequence. Please contact Kramer technical support for information.
19028	After the ALL button is used for routing, the routing is implemented correctly, but upon the next power cycle, the video routing is not saved, only the audio routing is saved.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

QC ID	Deferred Bug Description
	Workaround: To retain an "ALL" operation routing, even after a power cycle, use the Protocol 3000 command or embedded web page to perform the "ALL" routing.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.3\_0000 1.1.2



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	1.3_0000 1.1.2	January 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** January 17, 2021

**Reference:** 17041b

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88H2A	Any	Yes	Yes

### Technical Notes:

Fixed several bugs.

Added modification.

### Codependency with Other Products and Software:

There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	1.3_0000 1.1.2	January 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** January 17, 2021

**Reference:** 17041b

### New Modifications:

QC ID	Modification Description
	Improved compatibility with DGKAT products (PT-571 & PT-572+).

### Bugs Fixed:

QC ID	Fixed Bug Description
16276	Timeout setting for 5V_off is not available when video is lost on the input. However, when the input cable is disconnected, 5V_off works properly.
17272	Web UI browsing is recommended using Chrome, Safari or Firefox. Browsing through IE11 64 may fail.
17601	Executing the NAME P3K command results in the loss of the TCP port connection.
17926	Web UI - On "Switching" page Video Mute icon checkbox does not toggle back to Video Unmute.
17927	Web UI - On "Timeout settings" page "Support Audio Only" switch does not function.
17941	Output with Audio Only ON doesn't stop 5V output when video and audio inputs are removed.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15437	Auto Switching may occur unexpectedly following EDID copy operation.
17253	When UDP port is changed from the default of 50000, Kramer Network not automatically discover the device.
17275	The API command uses a generic volume span of 0 to 100 and the web UI volume slider uses -50dB to 25dB.
17276	Web Login – When activating 'Authentication' you need to define a new password (default is empty string).
17572	After changing the IP address via the web UI a page refresh is required.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

QC ID	Deferred Bug Description
18970	A failed Firmware upgrade due to accidental power shutdown requires system recovery sequence. Please contact Kramer technical support for information.
19028	After the ALL button is used for routing, the routing is implemented correctly, but upon the next power cycle, the video routing is not saved, only the audio routing is saved. Workaround: To retain an "ALL" operation routing, even after a power cycle, use the Protocol 3000 command or embedded web page to perform the "ALL" routing.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.2\_0000 1.1.2



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	1.2_0000 1.1.2	June 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 1, 2020

**Reference:** 07528

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88H2A	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-88H2A

**Current Version:**

Type	Number	Date
Firmware	1.2_0000 1.1.2	June 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 1, 2020

**Reference:** 07528

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/VS-88H2A](http://www.kramerav.com/manual/VS-88H2A)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15437	Auto Switching may occur unexpectedly following EDID copy operation.
16276	Timeout setting for 5V_off is not available when video is lost on the input. However, when the input cable is disconnected, 5V_off works properly.
17253	When UDP port is changed from the default of 50000, Kramer Network not automatically discover the device.
17272	Web UI browsing is recommended using Chrome, Safari or Firefox. Browsing through IE11 64 may fail.
17275	The API command uses a generic volume span of 0 to 100 and the web UI volume slider uses -50dB to 25dB.
17276	Web Login – When activating 'Authentication' you need to define a new password (default is empty string).
17572	After changing the IP address via the web UI a page refresh is required.
17601	Executing the NAME P3K command results in the loss of the TCP port connection.
17926	Web UI - On "Switching" page Video Mute icon checkbox does not toggle back to Video Unmute.
17927	Web UI - On "Timeout settings" page "Support Audio Only" switch does not function.
17941	Output with Audio Only ON doesn't stop 5V output when video and audio inputs are removed.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

Preceding Version: N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)