

**Product Name**: WP-580TXR, WP-580RXR **Current Version:** F – 1.30.90 (Valens)

Version Date: July 2014

Reference: 7507

**Release Type:** 

$\boxtimes$	Firmware	Software	Hardware	New Product

### **Kramer Products Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-580TXR	No	Yes	N/A
WP-580RXR	No	Yes	N/A

### **Technical Notes:**

- This is a release fixes a missing video problem.
- This upgrade can be done only in the Kramer office. Please contact your Kramer dealer for details.

# **Codependency with Other Products and Software:**

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerel.com</u>
Web: <u>www.kramerelectronics.com</u>



**Product Name**: WP-580TXR, WP-580RXR

**Current Version:** F - 1.30.90 (Valens)

Version Date: July 2014

Reference: 7507

### Fixes:

• When the transmitter and receiver were powered up together, sometimes the monitor did not receive video.

## **Known Issues:**

• There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com



**Product Name**: TP-580TXR, TP-580RXR

**Current Version:** NP – 1.0 **Version Date**: April 2013

Reference: 2499

This is a release note for a new product.

• Kramer strongly recommends using shielded cable with this product.

### **Known Issues:**

• There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com