



Product Name: VP-734

Current Version:

Ver.Type	Ver No.	Date
Firmware	VTR1.17 VTX1.05 VPC1.09	September 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2016

Reference: 10785

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-734	Any	Yes	N/A

Technical Notes:

- EDID was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-734

Current Version:

Ver.Type	Ver No.	Date
Firmware	VTR1.17 VTX1.05 VPC1.09	September 2016
Software	—	—
Web	—	—
Hardware	—	—

RN Date: September 2016

Reference: 10785

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
	EDID problems were fixed

Bugs to be Fixed in Future Version:

QC ID	Description
5777	Password is not default value after factory reset
5844	Wrong title of volume bar
5897	OSD changes do not appear in WEB until refreshed
5898	Different minimum size of the window can be defined via WEB and OSD
5901	Max Volume Limit doesn't show on Web page and doesn't work with it
5907	Web loading takes too much time
5908	When muted, scrolling the slider must unmute the audio on the Web page
5909	After a preset was chosen on Web page, you must click the Save or Recall button to close the preset screen
5934	There are 'Label' issues
5941	Auto switch on/off is missing from the 'Input Settings' Web page
5942	The Input tab has an 'Auto switch' option and the Setup has 'Auto-switch priority' option - unify the terms



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



QC ID	Description
5945	Any change of Horizontal Pan or Vertical Pan made via Web page didn't apply to device.
5972	Web EDID Management issues
6012	Temporal NR is not available in any format or with any input resolution.
6013	Mosquito and Block NR are not available with digital and VGA inputs.
6061	Audio outputs on both embedded and analog outputs in spite of the Output HDMI Type being DVI
6104	Front panel buttons do not react robustly to being pressed
6106	Changing Auto-switch priority for any input gets two different priorities
6117	By scaling from 2K input resolution to 4K output resolution the output image is corrupted
6127	Using Mac as a source, 1080p@60 displays instead of some of the device resolutions
6128	The HDMI input does not support 480i@60 and 1080p@24 resolutions
6130	Missing IP and Gateway validation
6133	Password prompt appears when 'Activate Security' is off
6135	After setting 'Activate Security' on and reloading the page, it appears as set to off

Known Limitations (including compatibility limitations):

QC ID	Description
5629	Compliance test: fail on 4k / pass with 1080p.
5632	All resolutions test: 840Hxl - no picture with 1360x768@60hz (Audio exist)
5637	Problem in 'BLANK' and 'FREEZE'
596	When recalling any saved preset via Web, the device resets.
5910	On Web page, the volume can be changed from min to max value in one click.
5947	There is a flashing path at the bottom of the monitor DELL-U2711 when Overscan is on
6012	Temporal NR isn't available in any format input input resolution.
6013	Mosquito and Block NR isn't available with digital and VGA inputs.
6106	Changing Auto-switch priority for any input gives two different priorities
6127	Using Mac as a source the device displays 1080p@60 instead of some resolutions.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-734
Current Version: NP – 1.0
Version Date: February 2016
Reference: 8206

This is a release note for a new product.

Known Issues:

- Maximum Volume Limit is not shown on the Web page.
- Input labeling issues on the Web page.
- Auto switch on/off is missing on the 'Input Settings' Web page.
- 480i@60 and 1080P@24 resolutions on HDMI input not supported.
- Missing IP and Gateway validation.
- Password prompt appears when 'Activate Security' is off.
- After setting 'Activate Security' on and reloading the page, it appears as off setting.
- Issues with IE10.
- Cannot increase the size of the picture via the Web.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com