Release Notes

Product Name: **DSP-62-AEC**

Current Version:

Type	Number	Date
Firmware	2.0.64652	October 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 25, 2023
Reference: 19284

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-AEC	Any	Yes	Yes

Summary:

- Fixed a bug.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: **DSP-62-AEC**

Current Version:

Type	Number	Date
Firmware	2.0.64652	October 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 25, 2023
Reference: 19284

New Features:

N/A

Modifications:

N/A

Dropped Features:

N/A

Bugs Fixed:

QC ID	Fixed Bug Description
KMR-85425	Not getting USB audio when connected with HDMI or Analog inputs. – Issue fixed.

Bugs to Fix in Future Versions:

N/A

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18733	Firmware upgrade via RS-232 is not supported in this product.
18856	Web Pages – When an input or output label of more than 20 characters is entered, no error message appears, and the old name remains.

Preceding Version: 2.0.63510

Release Notes History

Product Name: **DSP-62-AEC**

Current Version:

Type	Number	Date
Firmware	2.0.63510	May 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 28, 2023
Reference: 18918

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-AEC	Any	Yes	Yes

Summary:

- Added feature(s).
- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name:	**DSP-62-AEC**		
Current Version:	**Type**	**Number**	**Date**
	Firmware	2.0.63510	May 2023
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date:　　　　May 28, 2023
Reference:　　　　18918

New Features:

	New Feature Description
	Added Web UI new branding

Bugs to Fix in Future Versions:

ID	**Deferred Bug Description**
	None listed.

Known Limitations (including compatibility limitations):

ID	**Limitation Description**
18733	Firmware upgrade via RS-232 is not supported in this product.
18856	Web Pages – When an input or output label of more than 20 characters is entered, no error message appears, and the old name remains.

Preceding Version: 2.0.63469

Release Notes History

Product Name: **DSP-62-AEC**

Current Version:

Type	Number	Date
Firmware	2.0.63469	December 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 15, 2022
Reference: 18606

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-AEC	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: **DSP-62-AEC**

Current Version:

Type	Number	Date
Firmware	2.0.63469	December 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 15, 2022
Reference: 18606

New Features:

	New Feature Description
	Selectable AEC reference and any mix of input or output
	Auto Switching with priority and last connected policies.
	48Khz auto-adapting on USB audio output
	GPIO ports support.
	Web-UI enhancements: EDID Management, Time and Date setting.
	Various Bug Fixes

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18733	Firmware upgrade via RS-232 is not supported in this product.
18856	Web Pages – When an input or output label of more than 20 characters is entered, no error message appears, and the old name remains.

Preceding Version: 1.0.58843

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: **DSP-62-AEC**

Current Version:

| Type	Number	Date
Firmware	1.0.58843	December 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 29, 2020
Reference: 17132

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-AEC	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

ⓘ Use the web pages to perform firmware upgrade. Firmware upgrade via RS-232 is not supported in this product.

ⓘ When you select the Force RGB or 2LCPM Support checkbox, the change takes affect only upon the next time you copy an EDID.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Release Notes History

	Type	Number	Date
Product Name: **DSP-62-AEC**			
Current Version:	Firmware	1.0.58843	December 2020
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: December 29, 2020
Reference: 17132

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/DSP-62-AEC

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18733	Firmware upgrade via RS-232 is not supported in this product.
18856	Web Pages – When an input or output label of more than 20 characters is entered, no error message appears, and the old name remains.

Preceding Version: N/A