KRAMER

Release Note

Product Name: VCO-1, VCO-8, VCO-16

Current Version:

Ver.Type	Ver No.	Date
Firmware	5.37	January 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2018

Reference: 13638

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VCO-1	Any	Yes	N/A
VCO-8	Any	Yes	N/A
VCO-16	Any	Yes	N/A

Technical Notes:

- Fixed an audio issue.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER

Release Note

Product Name: **VCO-1, VCO-8, VCO-16**

Current Version:

Ver.Type	Ver No.	Date
Firmware	5.37	January 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **January 2018**

Reference: **13638**

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed an audio issue at the loop output.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9748	No DHCP option on VCO devices.

Known Limitations (including compatibility limitations):

QC ID	Description
9754	FW Upgrading by K-Upload is enabled after closing the VCO Setup or any other control application.
9982	VCO will return 60Hz response also if the input signal is 59Hz.

Preceding Version: F – 5.35

KRAMER

Release Note History

Product Name: VCO-1, VCO-8, VCO-16

Current Version:

Ver.Type	Ver No.	Date
Firmware	5.35	December 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **December 2017**

Reference: **13351**

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VCO-1	Any	Yes	N/A
VCO-8	Any	Yes	N/A
VCO-16	Any	Yes	N/A

Technical Notes:

- Fixed bugs.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER

Release Note History

Product Name: **VCO-1, VCO-8, VCO-16**

Current Version:

Ver.Type	Ver No.	Date
Firmware	5.35	December 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **December 2017**

Reference: **13351**

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
10677	Some types of flash drives are not recognized by VCO devices.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9748	No DHCP option on VCO devices.

Known Limitations (including compatibility limitations):

QC ID	Description
9754	FW Upgrading by K-Upload is enabled after closing the VCO Setup or any other control application.
9982	VCO will return 60Hz response also if the input signal is 59Hz.

Preceding Version: F – Old Version

Release Note History

Product Name: **VCO-1, VCO-8, VCO-16**

Current Version:

Ver.Type	Ver No.	Date
Firmware	Old Version	December 2016
Software	Build 178	December 2016
Web	–	–
Hardware	–	–

RN Date: **December 2016**

Reference: **9908**

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VCO-1	N/A	N/A	N/A
VCO-8	N/A	N/A	N/A
VCO-16	N/A	N/A	N/A

Technical Notes:

- This is a release note for new products.

Codependency with Other Products and Software:

There is no codependency with other products or software.

Release Note History

Product Name: VCO-1, VCO-8, VCO-16

Current Version:

Ver.Type	Ver No.	Date
Firmware	Old Version	December 2016
Software	Build 178	December 2016
Web	–	–
Hardware	–	–

RN Date: **December 2016**

Reference: **9908**

This is a release note for a new product. For a list of new product features see:

http://www.kramerav.com/downloads/VCO-1

Bugs to be Fixed in Future Version:

QC ID	Description
9748	No DHCP option on VCO devices
9754	Upgrading the VCO-1 while app is on and binder is impossible
9982	Inaccurate response for the "#y 1,301,0" command (returns resolution number of input)

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A