**Current Firmware Version:** 6191

**Version Date:** May 2012

**Reference:** 3176

**Kramer Products Affected:**

| Product Name | Minimum FW version for upgrade | Recommended for all units | Only if added features are required |
|---|---|---|---|
| VP-81K | Any | Yes | – |
| | | | |

**Technical Notes:**

- A bug in automatic mode was fixed.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.

**Current Firmware Version:**    6191

**Version Date:**    May 2012

**Reference:**    3176

The following changes were made in this version:

## Fixes:

- A bug in automatic mode was fixed: the unit did not switch to a second input when the first input was disconnected. It now switches correctly.

## Known Issues:

- There are no known issues.

**Preceding Firmware Version:**  5577

**Preceding Firmware Version:** 5577

**Version Date:** December 2011

**Reference:** 1596

The following changes were made in this version:

**Fixes:**

- Bugs in RS-232 / Ethernet protocol communication were fixed.
- Bugs in audio volume control via the RS-232 / Ethernet were fixed.
- An IR control problem was fixed: when the machine number of an IR command is different from unit machine number.

**Known Issues:**

- There are no known issues.

**Preceding Firmware Version:** N/A