



Product Name: DIP-30
Current Version: F - 1.9.25164, Web - 2.0.9
Version Date: January 2016
Reference: 9695

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DIP-30	No	Yes	N/A

Technical Notes:

- Switching time was improved.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: DIP-30
Current Version: F - 1.9.25164, Web - 2.0.9
Version Date: January 2016
Reference: 9695

The following changes were made in this version:

Modifications:

- Switching time was improved.

Known Issues:

- AV-SW-TIMEOUT works for all video/audio signal changes except for:
#1 - New video signal detected and #3 - Audio signal detected:

#AV-SW-TIMEOUT 1,11 ~01@AV-SW-TIMEOUT 1 ERR 003

#AV-SW-TIMEOUT 3,11 ~01@AV-SW-TIMEOUT 3 ERR 003

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: DIP-20
Preceding Version: NP – 1.0
Version Date: December 2015
Reference: 7756

This is a release note for a new product.

Known Issues:

- AV-SW-TIMEOUT works for all video/audio signal changes except for:
#1 - New video signal detected and #3 - Audio signal detected:

#AV-SW-TIMEOUT 1,11 ~01@AV-SW-TIMEOUT 1 ERR 003
#AV-SW-TIMEOUT 3,11 ~01@AV-SW-TIMEOUT 3 ERR 003

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com