



Product Name: VP-794
Current Version: F – 293D-10484
Version Date: June 2016
Reference: 10736

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-794	Any	Yes	Yes

Technical Notes:

- SDI audio and SDI position were fixed, the power down sequence was improved and Web server maintenance was performed.
- Features of this firmware are identical to firmware 293C-10290
- This firmware supports new HW beginning with serial number C328643.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VP-794
Current Version: F – 293D-10484
Version Date: June 2016
Reference: 10736

The following changes were made in this version:

Fixes:

- SDI audio was fixed. Audio was not recognized (and muted) from certain sources due to incomplete understanding of header information.
- The power down sequence was improved.
- The Web server was maintained.
- Illegal SDI horizontal and vertical position values were trapped.

Known Issues:

- There are no known issues.

Preceding Version: F – 293C-10290



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: VP-794
Preceding Version: F – 293C-10290
Version Date: May 2016
Reference: 10419

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-794	Any	Yes	Yes

Technical Notes:

- SDI audio and SDI position were fixed, the power down sequence was improved and Web server maintenance was performed.
- Features of this firmware are identical to the following firmware 293D-10484.
- This firmware supports older HW up to serial number C328642.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelectronics.com

Web: www.kramerelectronics.com



Product Name: VP-794
Preceding Version: F – 293C-10290
Version Date: May 2016
Reference: 10419

The following changes were made in this version:

Fixes:

- SDI audio was fixed. Audio was not recognized (and muted) from certain sources due to incomplete understanding of header information.
- The power down sequence was improved.
- The Web server was maintained.
- Illegal SDI horizontal and vertical position values were trapped.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com