



Product Name: VP-444
Current Version: F – 1.22 (beta)
Version Date: February 2015
Reference: 4444

Release Type:

☐ Firmware ☐ Software ☐ Hardware ☒ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-444	No	Yes	N/A

Technical Notes:

- Several known issues and various bugs were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelectronics.com

Web: www.kramerelectronics.com



Product Name: VP-444
Current Version: F – 1.22 (beta)
Version Date: February 2015
Reference: 4444

The following changes were made in this version:

Added Features:

- Options to blank the video output were added.
- Supports audio even if video is not present.

Fixes:

- A bug in the "Last Connected" feature was fixed.
- Now includes front-panel serial port echoing.
- P3K is now supported when connected via UDP.
- Allows use of front panel buttons while the OSD's volume value is displayed.
- Fixes a bug that sometimes affected EDID file copying.
- Minor bugs were fixed.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Known Issues:

- The talk-over feature is not yet implemented.
- Performing several actions on the device can cause the Web page to stop controlling the unit.
- There may be a "popping" noise when cycling power.
- The input resolution may display incorrectly after copying the EDID to a MacBook's input
- In a few cases, the first characters of the input name are deleted.

Preceding Version: 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-444
Preceding Version: NP – 1.0
Version Date: January 2015 (Ver 2)
Reference: 5473

This is a release note for a new product.

Known Issues:

- The talk-over feature is not yet implemented.
- P3K is not yet supported when connected via UDP.
- Performing several actions on the device can cause the Web page to stop controlling the unit.
- There may be a "popping" noise when cycling power.
- The input resolution may display incorrectly after copying the EDID to a MacBook's input
- The "Last Connected" feature has issues if the current input is unplugged.
- No echo is sent on the serial port when controlled via the front panel.
- The front panel's buttons are disabled while the OSD's volume value is displayed.
- There may be differences between the original EDID and copied EDID files.
- In a few cases, the first characters of the input name are deleted.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com