



**Product Name:** VS-44HN  
**Current Version:** F – 2.3  
**Version Date:** October 2013  
**Reference:** 6018

**Release Type:**

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-44HN	Any	Yes	N/A

**Technical Notes:**

- A command problem was fixed.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-44HN  
**Current Version:** F – 2.3  
**Version Date:** October 2013  
**Reference:** 6018

The following changes were made in this version:

**Fixes:**

- A bug in the GEDID command was fixed.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 2.2



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-44HN  
**Preceding Version:** F – 2.2  
**Version Date:** March 2013  
**Reference:** 5073

The following changes were made in this version:

**Added Features:**

- A Reset command was added for Protocol 2000.

**Fixes:**

- When storing from the keypad, the device did not send the relevant command to K-Router.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F - 1.3



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Preceding Version:** F - 1.3  
**Version Date:** August 2012 (Update)  
**Reference:** 3848

The following changes were made in this version:

**Fixes:**

- The numbering of the setups under front panel buttons was in the wrong order.
- When one of the outputs was set off K-Router reported that all outputs were off.

**Known Issues:**

- The IR remote control does not work when the device is set to Protocol 3000. It does work when the device is set to Protocol 2000.

**Preceding Firmware Version:** N/A



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)