KRAMER ELECTRONICS RELEASE NOTE

Product Name: 840Hxl Control Software

Current Version: S – 1.0.18.0

Version Date: February 2016

Reference: 10152

Release Type:

☐ Firmware   ☒ Software   ☐ Hardware   ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
840Hxl	N/A	N/A	N/A

Technical Notes:

- EDID can be read even without receiving a hot plug signal.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Product Name: 840Hxl Control Software

Current Version: S – 1.0.18.0

Version Date: February 2016

Reference: 10152

The following changes were made in this version:

Modifications:

- EDID can now be read even without receiving a hot plug signal.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.17.0

Product Name: 840Hxl Control Software
Preceding Version: S – 1.0.17.0
Version Date: February 2016
Reference: 10035

The following changes were made in this version:

Added Features:

- New resolutions were added including user-defined resolutions.
- A pattern cycle button was added.

Modifications:

- Major changes in the main window.
- Unsupported HDCP is indicated in red.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.14.0

Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.14.0

Version Date: September 2014

Reference: 7659

The following changes were made in this version:

Added Features:

- Shortcut buttons were added for the following resolutions:

  UXGA DVI
  XGA DVI
  1280x1024 RGB Multi

- EDID information can be displayed by pressing F5.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.13.0

Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.13.0

Version Date: June 2014

Reference: 7266, 7386

The following changes were made in this version:

Added Features:

- A shortcut buttons were added for the following resolutions:

    1600x1200 (RGB)

    1024x768 (RGB)

    1280x1024 (RGB)

    1080p (HDCP/YUV422)

    1080p (HDCP/DVI)

    1080p (DVI)

Modifications:

- The refresh rate for 1280x1024 was changed from 75Hz to 60Hz.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.9.0

Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.9.0

Version Date: March 2014

Reference: 7024

The following changes were made in this version:

Added Features:

- Read and display EDID data of the device connected to the output of the 840Hxl.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.6.0

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: 840Hxl Control Software

Preceding Version: 1.0.6.0

Version Date: May 2012

Reference: 3303

The following changes were made in this version:

Fixes:

- Some resolution pattern icons that were transparent on some computers were fixed.

Known Issues:

- There are no known issues.

Preceding Software Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com