Release Notes

Product Name: **SWT3-31-HU**

Current Version:

Type	Number	Date
Firmware	1.0.65072	January 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 1, 2024
Reference: 19443

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Replaced Products:

N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: **SWT3-31-HU**

Current Version:

Type	Number	Date
Firmware	1.0.65072	January 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 1, 2024
Reference: 19443

The following changes were made in this version:

New Features:

	New Feature Description
	Configurable LAN connection via USB-C.
	Auto EDID-support for 2-channel audio.

Modifications:

N/A

Dropped Features:

N/A

Bugs Fixed:

ID	Fixed Bug Description
2016	Detected buttons click is longer than standard.

Bugs to Fix in Future Versions:

N/A

Known Limitations (including compatibility limitations):

ID	Description
85605	Macbook Pro improper USB-C LAN connection. MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver. https://www.asix.com.tw/en/product/USBEthernet/High-Speed_USB_Ethernet/AX88772C

Release Notes

Preceding Version: N/A

Release Notes History

Product Name: **SWT3-31-HU**

Current Version:

Type	Number	Date
Firmware	1.0.64477	October 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 25, 2023

Reference:

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-31-HU	N/A	N/A	N/A

Summary:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Replaced Products:

- N/A

Release Notes History

Product Name: **SWT3-31-HU**

Current Version:

Type	Number	Date
Firmware	1.0.64477	October 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 25, 2023

Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-31-HU

Issues to Fix in Future Versions:

ID	Deferred Issue Description
85394	Time location isn't disabled for disabled NTP server.
	Incorrect P3K time query response.
	No connection of active host with newly plugged USB device. Workaround: Re-switch active host.
85256	Web-UI gateway active/inactive option is unsupported.
85246	Input signal status does not have port numbers near signal name at Web UI.
85244	Few web-UI configured attributes are not exported/imported.
84782	After device restart, Web page should be refreshed manually.
84431	Web-UI color depth is not configurable.
83357	Long delay on initial web-UI landing page load.
84573	After device restart, Web page should be refreshed manually.
84200	No command name edit when contains 2 spaces.
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.

Known Limitations (including compatibility limitations):

ID	Limitation Description
83350	Default hostname may contain further truncated model name to comply with its standard-required uniqueness.
85263	Web-UI action command length is up to 300 characters.

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History