Product Name: VIA

Current Version:

Type	Number	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	–
Client Version*	1.0.0.1	February 2024
* Client Version release is now separated from the GWs versions.		

RN Date: February 4, 2024
Reference: 019536

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VIA Go^2	3.3.0722.1240	Yes	No
VIA Connect^2	3.3.0722.1240	Yes	No
VIA Campus^2	3.3.0722.1240	Yes	No
VIA Campus^2 Plus	3.3.0722.1240	Yes	No
VIA Go	3.3.0722.1240	Yes	No
VIA Connect Pro	3.3.0722.1240	Yes	No
VIA Connect Plus	3.3.0722.1240	Yes	No
VIA Campus	3.3.0722.1240	Yes	No

Summary:

- Fixed bugs.
- Added feature(s).

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Product Name:	VIA		
Current Version:	**Type**	**Number**	**Date**
	Firmware	–	–
	Software	–	–
	Web	–	–
	Hardware	–	–
	Client Version*	1.0.0.1	February 2024
	* Client Version release is now separated from the GWs versions.		

RN Date: February 4, 2024
Reference: 019536

New Features:

N/A

Modifications:

N/A

Dropped Features:

N/A

Bugs Fixed:

ID	Fixed Bug Description
6493	Presentation of Mac client not working through MAC OS Sonoma (version 14).

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Enhancements:

| ID	Deferred Bug Description
	Added a new icon to enable client upgrade when a new version is available.
	An updated Versa icon.
	Action tiles UI modifications to sync with Session Manager – 3rd party application is now under Screen → Action Tiles.

User Interface Enhancements:

New Versa icon

Icon to enable client upgrade when available (exist only when new version is available)

3rd party application under Screen → Action Tiles: