Product Name: TP-576

Current Version: F – 1.1

Version Date: October 2013

Reference: 6405

Release Type:

☒ Firmware ☐ Software ☒ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-576	Any	Yes	N/A

Technical Notes:

- A problem with the IR transmission was fixed and the default EDID was changed.
- This change requires both firmware and hardware changes. Please contact your Kramer representative for details.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: TP-576

Current Version: F – 1.1

Version Date: October 2013

Reference: 6405

The following changes were made in this version:

Fixes:

- A problem was fixed in which the IR transmission sometimes did not work.

Modifications:

- “KRM” was changed to “KMR” in the default EDID.

Known Issues:

- 1600x1200 is the maximum resolution supported by DGKat however; HDCP content on long cable runs may cause occasional image instability at some installations.

Preceding Version: 1.0

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: TP-576

Preceding Version: NP – 1.0

Version Date: July 2011

Reference: 158

This is a release note for a new product.

Known Issues:

- 1600x1200 is the maximum resolution supported by DGKat however; HDCP content on long cable runs may cause occasional image instability at some installations.

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com