# KRAMER

# Release Notes

**Product Name:** VP-506

**Current Version:**

| Type | Number | Date |
|------|--------|------|
| Firmware | 1.13 | May 2021 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

**RN Date:** May 30, 2021
**Reference:** 17513

## Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|-------------------------------|---------------------------|-------------------------------------|
| VP-506 | Any | Yes | Yes |

## Technical Notes:

- Fixed a bug.

## Codependency with Other Products and Software:

- There is no codependency with other products or software.

# KRAMER

# Release Notes

**Product Name:**    **VP-506**

**Current Version:**

| Type | Number | Date |
|---|---|---|
| Firmware | 1.13 | May 2021 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

**RN Date:**    May 30, 2021
**Reference:**    17513

The following changes were made in this version:

## Bugs Fixed:

| QC ID | Fixed Bug Description |
|---|---|
| | Fixed color burst issue, adding missing burst pulses during the vertical blanking period. |

## Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|---|---|
| | None listed |

## Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|---|---|
| | None listed |

**Preceding Version**: **1.12**

# Release Notes History

**Product Name**: VP-506

**Current Version:** F – 1.12

**Version Date**: September 2015

**Reference**: 8693

## Release Type:

☒ Firmware   ☐ Software ☐ Hardware   ☐ New Product

## Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|---|---|---|---|
| VP-506 | | Yes | N/A |
| | | | |

## Technical Notes:

- Test pattern color problem fixed, new resolution support added and manufacturer ID changed.

## Codependency with Other Products and Software:

- There is no codependency with other products or software.

# Release Notes History

**Product Name**:    VP-506

**Current Version:**  F – 1.12

**Version Date**:    September 2015

**Reference**:  8693

The following changes were made in this version:

## Added Features:

- Support for 1366x768@60 resolution was added.

## Fixes:

- Abnormal purple color showing on gray test pattern was fixed.

## Modifications:

- Manufacturer ID changed to KMR.

## Known Issues:

- There are no known issues.

**Preceding Version:**  N/A