Current Firmware Version: 1.7

Version Date: June 2012

Reference: 3313

Kramer Products Affected:

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if added features are required
VS-3232V, VS-3232Vxl	Any	Yes	–

Technical Notes:

- This version is now compatible with K-Router.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Current Firmware Version: 1.7

Version Date: June 2012

Reference: 3313

The following changes were made in this version:

Fixes:

- This version was made compatible with K-Router.

Known Issues:

- There are no known issues.

Preceding Firmware Version: N/A