Product Name: MV-5

Current Version: S – 1.0.0.10

Version Date: April 2015

Reference: 8644

Release Type:

☐ Firmware   ☒ Software   ☐ Hardware   ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MV-5	Any	Yes	N/A

Technical Notes:

- A configuration load problem was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-5

Current Version: S – 1.0.0.10

Version Date: April 2015

Reference: 8644

The following changes were made in this version:

Fixes:

- Labels are saved when the configuration loads.

Known Issues:

- The MV-5 PC application does not display correctly on resolutions lower than 1024x768.

- Changing the screen resolution while the MV-5 PC application is open may result in improper display of the application. In this case shut down the unit and restart it.

- When cascading two units (output from one unit connected to an input of the other unit), the HDCP indication LED on the first unit may not display the correct information.

Preceding Version: F – 1.0.0.8

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-5

Preceding Version: F – 1.0.0.8

Version Date: July 2014

Reference: 7469

The following changes were made in this version:

Added Features:

- Disconnecting from the MV-5 is now indicated.
- A non-MV-5 device cannot be connected.
- Windows can be resized in any direction (left and top added).
- Windows can be positioned outside of visible area.

Fixes:

- Output resolution window resizing was fixed.
- The Layer section was fixed.
- The aspect ratio section was fixed.
- The setup-store option was fixed.
- All parameters that were not synchronized with the device were fixed.
- Firmware upload via the application was fixed.
- Validation was added when the user enters an IP/Mask/Getaway address.
- Web/GUI limiting of windows width/height was added.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Known Issues:

- The MV-5 PC application does not display correctly on resolutions lower than 1024x768.

- Changing the screen resolution while the MV-5 PC application is open may result in improper display of the application. In this case shut down the unit and restart it.

- When cascading two units (output from one unit connected to an input of the other unit), the HDCP indication LED on the first unit may not display the correct information.

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-5

Current Version: NP – 1.0

Version Date: May 2014

Reference: 4400

This is a release note for a new product.

Known Issues:

- The MV-5 PC application does not display correctly on resolutions lower than 1024x768.

- Changing the screen resolution while the MV-5 PC application is open may result in improper display of the application. In this case shut down the unit and restart it.

- It is not possible to install the MV-5 PC application and the MV-6 PC application on the same system.

- When cascading two units (output from one unit connected to an input of the other unit), the HDCP indication LED on the first unit may not display the correct information.

Preceding Version: N/A