KRAMER ELECTRONICS RELEASE NOTE

Product Name: **VIA GO**

Current Version:

| Ver.Type	Ver No.	Date
Firmware	2.0.0916.788	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **January 2017**

Reference: **11827**

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VIA GO	2.0.0916.788	MANDATORY	N/A

Technical Notes:

- This patch must be applied to all units running a minimum version of 2.0.0916.788. Units running older version than this must be reimaged to this latest version.

- This patch fixes bugs in Wi-Fi client mode and in the FW upgrade process.

- There is no increment in the FW version, only the "Settings" module has a new version number. Once the patch is applied or the unit gets a new image file, enter the "Settings" module of the VIA GO menu and check for the following version 2.0.0117.279 as shown here:

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Product Name: **VIA GO**

Current Version:

Ver.Type	Ver No.	Date
Firmware	2.0.0916.788	
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **January 2017**

Reference: **11827**

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
	The unit didn't boot correctly and displayed a "No Network found" message when switching from Wi-Fi Client Mode to Access Point Mode.
	Bug in the upgrade FW process (for future FW releases)

Bugs to be Fixed in Future Version:

QC ID	Description
	The VIA client file gets a wrong name when downloaded using FireFox browser. The file is saved as "VIA.exe.txt" and can't run properly. Remove the ".txt" at the end of the file (to keep only "VIA.exe") before running it on your PC.

Known Limitations (including compatibility limitations):

QC ID	Description
	VIA GO can't be used in dual network mode when the Wi-Fi is set to Client mode.
	VIA Pad requires LAN settings of "Fixed IP" (DHCP not supported)

Preceding Version: F - 2.0.0916.788

Product Name: **VIA GO**

Preceding Version:

Ver.Type	Ver No.	Date
Firmware	2.0.0916.788	November 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **November 2016**

Reference: **11482**

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VIA GO	N/A – only image file	YES	N/A

Technical Notes:

- This is a new image file release for all VIA GO units after product is moved to "Active"

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name:	**VIA GO**		
Current Version:	**Ver.Type**	**Ver No.**	**Date**
	Firmware	2.0.0916.788	November 2016
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: **November 2016**

Reference: **11482**

Known Limitations (including compatibility limitations):

QC ID	Description
	No known limitations

Preceding Version: 2.0.0716.774

Product Name: VIA GO

Current Version:

Ver.Type	Ver No.	Date
Firmware	2.0.0716.774	September 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2016

Reference: 9447

This is a release note for a new product. For a list of new product features see:

http://www.kramerav.com/manual/VIA GO

Known Limitations (including compatibility limitations):

QC ID	Description
	No known limitations

Preceding Version: N/A