Product Name: VP-427

Current Version: F – 1.06

Version Date: March 2015

Reference: 8433

Release Type:

☒ Firmware   ☐ Software   ☐ Hardware   ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-427	Any	Yes	N/A

Technical Notes:

- An HDCP video problem was fixed and brightness was modified.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VP-427

Current Version: F – 1.06

Version Date: March 2015

Reference: 8433

This is a release note for a new product.

Fixes:

- An HDCP snow problem was fixed.

Modifications:

- The brightness range was changed to 0 to 50 with steps of 5.

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VP-427

Preceding Version: NP – 1.0

Version Date: May 2014

Reference: 4471

This is a release note for a new product.

Known Issues:

- There are no known issues.

Preceding Version: N/A