Product Name: VS-44HDCP

Current Version: F – 4.0

Version Date: June 2016

Reference: 10660

Release Type:

☒ Firmware   ☐ Software   ☐ Hardware   ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-44HDCP	Any	Yes	N/A

Technical Notes:

- Audio distortions were fixed.

Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.

Product Name: VS-44HDCP

Current Version: F – 4.0

Version Date: June 2016

Reference: 10660

The following changes were made in this version:

Fixes:

- While connecting a VS-311H to a VS-44HDCP and then switching between sources, the audio distorted.

Known Issues:

- There are no known issues.

Preceding Version: F – 3.3

Product Name: VS-44HDCP

Current Version: F – 3.3

Version Date: May 2015

Reference: 8777

The following changes were made in this version:

Fixes:

- Sometimes after reconnecting the HDMI input there was no audio in the HDMI output signal.

Known Issues:

- There are no known issues.

Preceding Version: F – 3.2

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VS-44HDCP

Current Version: F – 3.2

Version Date: October 2014

Reference: 7812

The following changes were made in this version:

Fixes:

- Sometimes after reconnecting the HDMI input there was no audio in the HDMI output signal.

Known Issues:

- On a non-HDCP monitor, when toggling between HDCP content to non-HDCP content, in some cases, the output remains blank even when the content is no longer HDCP.

Preceding Version: F – 3.2

Product Name: VS-44HDCP

Preceding Version: F – 3.2

Version Date: October 2014

Reference: 7812

The following changes were made in this version:

Fixes:

- Random DVI video noise with an 840Hxl was fixed.
- The model name is set for the device at the first power on.

Known Issues:

- On a non-HDCP monitor, when toggling between HDCP content to non-HDCP content, in some cases, the output remains blank even when the content is no longer HDCP.

Preceding Version: NP - 1.0

Product Name: VS-44HDCP

Current Version: NP – 1.0

Version Date: February 2014

Reference: 3631

This is a release note for a new product.

Known Issues:

* On a non-HDCP monitor, when toggling between HDCP content to non-HDCP content, in some cases, the output remains blank even when the content is no longer HDCP.

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com