

Product Name:	840Hxl Control	340Hxl Control Software			
Current Version:	S – 1.0.14.0				
Version Date:	September 201	eptember 2014			
Reference:	7659				
Release Type:					
Firmware	Software	Hardware			
Kramer Product Affected:					

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
840HxI	N/A	N/A	N/A

Technical Notes:

New shortcut buttons were added for resolutions.

Codependency with Other Products and Software:

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com $Web: \underline{\ \ www.kramerelectronics.com}$



Current Version: S - 1.0.14.0

Version Date: September 2014

Reference: 7659

The following changes were made in this version:

Added Features:

• Shortcut buttons were added for the following resolutions:

UXGA DVI XGA DVI 1280x1024 RGB Multi

• EDID information can be displayed by pressing F5.

Known Issues:

There are no known issues.

Preceding Version: S - 1.0.13.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: S – 1.0.13.0 **Version Date:** June 2014 **Reference:** 7266, 7386

The following changes were made in this version:

Added Features:

A shortcut buttons were added for the following resolutions:

1600x1200 (RGB)

1024x768 (RGB)

1280x1024 (RGB)

1080p (HDCP/YUV422)

1080p (HDCP/DVI)

1080p (DVI)

Modifications:

• The refresh rate for 1280x1024 was changed from 75Hz to 60Hz.

Known Issues:

There are no known issues.

Preceding Version: S - 1.0.9.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: S – 1.0.9.0 **Version Date:** March 2014

Reference: 7024

The following changes were made in this version:

Added Features:

• Read and display EDID data of the device connected to the output of the 840Hxl.

Known Issues:

There are no known issues.

Preceding Version: S - 1.0.6.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: 1.0.6.0

Version Date: May 2012

Reference: 3303

The following changes were made in this version:

Fixes:

 Some resolution pattern icons that were transparent on some computers were fixed.

Known Issues:

• There are no known issues.

Preceding Software Version: N/A



KRAMER ELECTRONICS, Ltd.