



Product Name: 840HxI Control Software

Current Version: S – 1.0.17.0

Version Date: February 2016

Reference: 10035

Release Type:

☐ Firmware ☒ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
840HxI	N/A	N/A	N/A

Technical Notes:

- A number of changes and improvements were made.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: 840Hxl Control Software
Current Version: S – 1.0.17.0
Version Date: February 2016
Reference: 10035

The following changes were made in this version:

Added Features:

- New resolutions were added including user-defined resolutions.
- A pattern cycle button was added.

Modifications:

- Major changes in the main window.
- Unsupported HDCP is indicated in red.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.14.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.14.0

Version Date: September 2014

Reference: 7659

The following changes were made in this version:

Added Features:

- Shortcut buttons were added for the following resolutions:
UXGA DVI
XGA DVI
1280x1024 RGB Multi
- EDID information can be displayed by pressing F5.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.13.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.13.0

Version Date: June 2014

Reference: 7266, 7386

The following changes were made in this version:

Added Features:

- A shortcut buttons were added for the following resolutions:
1600x1200 (RGB)
1024x768 (RGB)
1280x1024 (RGB)
1080p (HDCP/YUV422)
1080p (HDCP/DVI)
1080p (DVI)

Modifications:

- The refresh rate for 1280x1024 was changed from 75Hz to 60Hz.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.9.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: 840Hxl Control Software

Preceding Version: S – 1.0.9.0

Version Date: March 2014

Reference: 7024

The following changes were made in this version:

Added Features:

- Read and display EDID data of the device connected to the output of the 840Hxl.

Known Issues:

- There are no known issues.

Preceding Version: S – 1.0.6.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: 840Hxl Control Software
Preceding Version: 1.0.6.0
Version Date: May 2012
Reference: 3303

The following changes were made in this version:

Fixes:

- Some resolution pattern icons that were transparent on some computers were fixed.

Known Issues:

- There are no known issues.

Preceding Software Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com