

Product Name:
850 Control Software

Current Version:
S − 1.0.9.0

Version Date:
June 2015

Reference:
8227

Release Type:
Software
Hardware
New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
850	N/A	N/A	N/A

Technical Notes:

Digital signature was added.

Codependency with Other Products and Software:

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerel.com</u>
Web: <u>www.kramerelectronics.com</u>



Current Version:S - 1.0.9.0Version Date:June 2015

Reference: 8227

The following changes were made in this version:

Added Features:

• Digital signature was added.

Known Issues:

• There are no known issues.

Preceding Version: S - 1.0.8.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: S - 1.0.8.0 **Version Date:** July 2014

Reference: 7423

The following changes were made in this version:

Added Features:

- 850 Control Software is now automatically updated from the Web.
- Three shortcut buttons were added: UXGA Color Bar, UXGA RGB Ramp and UXGA Multi-Burst.

Known Issues:

• There are no known issues.

Preceding Version: S - 1.0.7.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: S – 1.0.7.0 **Version Date:** March 2014

Reference: 7053

The following changes were made in this version:

Added Features:

• EDID data is now displayed.

Known Issues:

• There are no known issues.

Preceding Version: S - 1.0.5.0



KRAMER ELECTRONICS, Ltd.



Preceding Version: 1.0.5.0

Version Date: May 2012

Reference: 3304

The following changes were made in this version:

Fixes:

 Some resolution pattern icons that were transparent on some computers were fixed.

Known Issues:

• There are no known issues.

Preceding Software Version: N/A



KRAMER ELECTRONICS, Ltd.