

Release Notes

Product Name: DSP-62-AEC

Current Version:

Type	Number	Date
Firmware	1.0.58843	December 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 29, 2020

Reference: 17132

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-AEC	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.



Use the web pages to perform firmware upgrade. Firmware upgrade via RS-232 is not supported in this product.



When you select the Force RGB or 2LCPM Support checkbox, the change takes affect only upon the next time you copy an EDID.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: DSP-62-AEC

Current Version:

Type	Number	Date
Firmware	1.0.58843	December 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 29, 2020

Reference: 17132

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/DSP-62-AEC

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18733	Firmware upgrade via RS-232 is not supported in this product.
18856	Web Pages – When an input or output label of more than 20 characters is entered, no error message appears, and the old name remains.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com