



Product Name: EDID Designer
Current Version: S – 4.5.0.97
Version Date: July 2016 (ver.2)
Reference: 9013

Release Type:

Firmware Software Hardware New Product

Technical Notes:

- Multiple bugs were fixed.
- **Note:** When installing this new version, you must de-install the previous version of EDID Designer before performing the new installation.
- If the new installation is not successful, see the installation procedure workaround at the end of this release note.

Supports the Following Devices:

Product Names		
DIP-20	VM-2UHD	VS-44HDCP
DIP-30	VM-3UHD	VS-44HN
PT-2C	VM-4HDT	VS-62D
TP-578H	VM-4UHD	VS-62H
TP-578HDCP	VM-8HN	VS-62HA
TP-588D	VP-31KSI	VS-88HFS
TP-590RXR	VP-81KSI	VS-88HN
TP-590TXR	VS-42HDCP	WP-20
VM-212DT	VS-42HN	WP-577VH
VM-214DT	VS-42UHD	WP-5VH2



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: EDID Designer
Current Version: S – 4.5.0.97
Version Date: July 2016 (ver.2)
Reference: 9013

The following changes were made in this version:

Bug Fixes:

- Various Ethernet and serial connection problems to Kramer devices were fixed.
- The auto update process was fixed.
- Empty file folder copy crashes were fixed.
- “Discard” did not work after removing extension blocks.
- Powering off and on the connected device caused problems when trying to copy the EDID.
- Default EDID problems were fixed.
- Deep color and audio tags remained after the extension information block was erased.
- Device support problems were fixed.
- Several minor bugs were fixed.

Known Issues:

- There is no backward compatibility to the VA-2H.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Installation Procedure Workaround:

- In case of a faulty installation, there is a known Microsoft hotfix (not always applied to all systems) as described here:
<https://support.microsoft.com/en-us/kb/2675806?wa=wsignin1.0>
- The following procedure, recommended by Microsoft, can fix a faulty installation:
<https://social.msdn.microsoft.com/Forums/windows/en-us/365f8c65-b413-428e-af93-f150059a185f/cannot-runinstalluninstall-a-clickonce-application>
- Try to delete the ClickOnce cache folder and install the .net application again. If the OS is Windows 7, the folder should be:
users\[username]\appdata\local\apps\2.0
- Remove the ClickOnce application manually.
- Delete the shortcuts of the ClickOnce application.
- Try to install again (run setup.exe)
- After manually removing the ClickOnce application, try to install it again.

Preceding Version: 1.0.0.79



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: EDID Designer
Preceding Version: S – 1.0.0.79
Version Date: June 2014
Reference: 7254

The following changes were made in this version:

Known Issues:

- There is no backward compatibility to the VA-2H.
- “Discard” doesn’t work when removing extension blocks.
- Powering off and on the connected device may cause problems when trying to copy the EDID after the device is on.
To solve the problem, disconnect and reconnect the device.

Preceding Version: 1.0.0.53



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Product Name: EDID Designer
Preceding Version: 1.0.0.53
Version Date: April 2012
Reference: 2236

The following changes were made in this version:

Fixes:

- A failure to save the EDID from download or pressing the save button was fixed.
- An Open Monitor EDID error in Windows 7 was fixed.
- A program crash when trying to read an EDID from a non-existing port was fixed.

Known Issues:

- There are no known issues.

Preceding Version: 1.0.0.43



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Software Name: EDID Designer
Preceding Version: 1.0.0.43
Version Date: September 2011

The following changes were made in this version:

Added Features:

- Support for the VA-2H was added.

Fixes:

- The status row now displays the current status.
- The "Command" menu is disabled when the status is "Disconnected".
- When illegal data is entered in numeric fields an error message is displayed.
- "Save EDID", "Save EDID as" and "Download to" were fixed to work properly.

Known Issues:

There are no known issues.

Preceding Version: 1.0.0.32



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com