

Product Name:	EXT3-C-WP-XR-T		
Current Version:	Туре	Number	Date
	Firmware	N/A	May 2024
	Software	-	-
	Web	-	-
	Hardware	03	May 2024
RN Date:	May 20, 2024		
Reference:	019679		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
EXT3-C-WP-XR-T	Any	Yes	Yes

Summary:

• Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name:	EXT3-C-WP-XR-T			
Current Version:	Туре	Number	Date	
	Firmware	N/A	May 2024	
	Software	-	-	
	Web	-	-	
	Hardware	03 (US), 02 (EU/UK)	May 2024	
RN Date:	May 20, 2024			
Reference:	019679			

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Potential improper USB-C connection for Lenovo laptop models (Gen2 or later). Workaround: Unplug/re-plug laptop till properly connected
This bug was fixed on HW Revision 03 (US) 02 (EU/UK) and higher. To check your device's product revision number, check the label on the box.	

Preceding Version: N/A





Product Name:	EXT3-C-WP-XR-T			
Current Version:	Туре	Number	Date	
	Firmware	N/A	November 2023	
	Software	-	—	
	Web	-	-	
	Hardware	-	_	
RN Date: Reference:	November 30, 2023 018765			

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
EXT3-C-WP-XR-T	N/A	N/A	N/A

Summary:

• This is a release note for a new product.

Codependency with Other Products and Software:

Product Name	Comments

• There is no codependency with other products or software.

Replaced Products:

Product Name	Comments





Product Name:	EXT3-C-WP-XR-T		
Current Version:	Туре	Number	Date
	Firmware	N/A	November 2023
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	November 30, 2023		
Reference:	018765		

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/EXT3-C-WP-XR-T

Bug Fixed in Current Version:

ID	Deferred Bug Description
83548	No USB device port 1 auto-disconnection on inactive host.

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

Preceding Version: N/A

