

Release Notes

Product Name: KDS-8F

Current Version: Type

| Туре | Number | Date |
|----------|--------|----------------|
| Firmware | 2.18 | September 2022 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: September 6, 2022

Reference: 18189

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------------|---------------------------|---|
| KDS-8F | Any | Yes | Yes |

Summary:

- · Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

There is no codependency with other products or software.



Release Notes

Product Name: KDS-8F

Current Version: Type

| Туре | Number | Date |
|----------|--------|----------------|
| Firmware | 2.18 | September 2022 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: September 6, 2022

Reference: 18189

New Features:

| | New Feature Description |
|---------|--|
| FW 2.11 | Add auto-switch feature |
| FW 2.12 | Improve video compatibility to PC Timing |

Modifications:

| QC ID | Modification Description |
|-------|----------------------------------|
| | Upgrade SDVoE FPGA firmware |
| | OSD vertical position definition |
| | Improved auto-switch. |

Bugs Fixed:

| QC ID | Fixed Bug Description |
|---------|------------------------------------|
| FW 2.18 | Remove extra message |
| | Fixed DVI color issue |
| | Fixed FPGA Init failure and retry. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |

Preceding Version: 3.5.2.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com



Release Notes History

Product Name: KDS-8F

Current Version: Type

| Туре | Number | Date |
|----------|---------|--------------|
| Firmware | 3.5.2.0 | October 2019 |
| Software | _ | _ |
| Web | _ | _ |
| Hardware | - | _ |

RN Date: October 10, 2019

Reference: 14085

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------------|---------------------------|---|
| KDS-8F | N/A | N/A | N/A |

Technical Notes:

- This is a release note for a new product.
- The following KDS-8F features are supported by Kramer Network version 2.2: Firmware upgrade, IP address configuration, Virtual Matrix and Video Wall setting.
- When using Kramer Network version 2.2 with KDS-8F devices, you may not use other models of KDS devices (KDS-EN/DEC5, KDS-EN/DEC6) in the same environment.
- To change the mode of operation between Genlock and Fast Switch or to configure the Multiview feature, <u>Blue River Agent Software</u> is required. The next version of Kramer Network will support these functions.

Codependency with Other Products and Software:

There is no codependency with other products or software.



Release Notes History

Product Name: KDS-8F

Current Version: Type

| Type | Number | Date |
|----------|---------|--------------|
| Firmware | 3.5.2.0 | October 2019 |
| Software | ı | _ |
| Web | _ | _ |
| Hardware | _ | _ |

RN Date: October 10, 2019

Reference: 14085

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/KDS-8F

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|---|
| 16085 | Compressed Audio (Dolby/DTS) input is not supported – if compressed audio |
| | is presented in the input, the resulting output is audio noise. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |

Preceding Version: N/A

E-mail: info@kramerav.com
Web: www.kramerav.com