

Product Name: SWT3-41-U-T

Current Version: Type Number Date

Type	Nullibel	Date
Firmware	1.0.65491	May 2024
Software	_	_
Web	_	_
Hardware	03	May 2024

**RN Date:** May 20, 2024

**Reference**: 019690

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U-T	Any	Yes	Yes

## **Summary:**

Fixed a bug.

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.



Product Name: SWT3-41-U-T

Current Version: Type Number Date

Type	Number	Date
Firmware	1.0.65491	May 2024
Software	ı	ı
Web	ı	ı
Hardware	03	May 2024

**RN Date:** May 20, 2024

**Reference**: 019690

The following changes were made in this version:

## **Bugs Fixed:**

QC ID Fixed Bug Description	
	Potential improper USB-C connection for Lenovo laptop models (Gen2 or later). Workaround: Unplug/re-plug laptop till properly connected
This bug was fixed on HW Revision 03 and higher. To check your device's product revision number, check the label on the box.	

## **Bugs to Fix in Future Versions:**

QC ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.

## **Known Limitations (including compatibility limitations):**

ID	Description
2443	Wait ~7sec prior to CAT cables connection, following change between CAT extension modes (dual links on 1 CAT cable or separate 2 CAT cables)
85605	Macbook Pro improper USB-C LAN connection.  MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver. <a href="https://www.asix.com.tw/en/product/USBEthernet/High-Speed USB Ethernet/AX88772C">https://www.asix.com.tw/en/product/USBEthernet/High-Speed USB Ethernet/AX88772C</a>

**Preceding Version**: 1.0.65098



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com



Product Name: SWT3-41-U-T

Current Version: Type Number Date

Type	Number	Date
Firmware	1.0.65098	January 2024
Software	_	_
Web	_	_
Hardware	_	_

RN Date: January 1, 2024

Reference: 19447

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U-T	Any	Yes	Yes

## **Summary:**

- Fixed a bug.
- Added feature(s).

#### **Codependency with Other Products and Software:**

• There is no codependency with other products or software.

#### **Replaced Products:**

N/A



Product Name: SWT3-41-U-T

Current Version: Type

Туре	Number	Date
Firmware	1.0.65098	January 2024
Software	_	_
Web	_	_
Hardware	_	_

RN Date: January 1, 2024

Reference: 19447

The following changes were made in this version:

#### **New Features:**

New Feature Description
Configurable LAN connection via USB-C.

#### **Modifications:**

ID	Modification Description
	Better stabilization of USB -C connection.

#### **Dropped Features:**

N/A

#### **Bugs Fixed:**

ID	Fixed Bug Description
2071	Detected buttons click is longer than standard.
1886	Proper ethernet extension post-reset.
2069	Stability of USB device connection.

#### **Bugs to Fix in Future Versions:**

ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.



KRAMER ELECTRONICS, Ltd.

E-mail: <a href="mailto:info@kramerav.com">info@kramerav.com</a>
Web: <a href="mailto:www.kramerav.com">www.kramerav.com</a>



## Known Limitations (including compatibility limitations):

ID	Description
85605	Macbook Pro improper USB-C LAN connection.
	MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver.
	https://www.asix.com.tw/en/product/USBEthernet/High-
	Speed USB Ethernet/AX88772C

Preceding Version: V1.0.64879



# **Release Notes History**

Product Name: SWT3-41-U-T

Current Version: Type

Туре	Number	Date
Firmware	V1.0.64879	November 2023
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 30, 2023

Reference:

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
	Opgrade		rtequired

#### **Summary:**

This is a release note for a new product.

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.

#### **Replaced Products:**

N/A

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>



# **Release Notes History**

Product Name: SWT3-41-U-T

Current Version: Type

Туре	Number	Date
Firmware	V1.0.64879	November 2023
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 30, 2023

Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-41-U-T

#### **Bugs to Fix in Future Versions:**

ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.
	Detected buttons click is longer than standard.
	Rarely, especially post power-cycle, plugged USB-C source is undetected.
	Workaround: Unplug & re-plug source.

Known Limitations (including compatibility limitations): N/A

Preceding Version: N/A