

Release Notes

Product Name: SWT3-41-U-T

Current Version:

Type	Number	Date
Firmware	1.0.65098	January 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 1, 2024

Reference: 19447

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U-T	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Replaced Products:

N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: SWT3-41-U-T

Current Version:

Type	Number	Date
Firmware	1.0.65098	January 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 1, 2024

Reference: 19447

The following changes were made in this version:

New Features:

	New Feature Description
	Configurable LAN connection via USB-C.

Modifications:

ID	Modification Description
	Better stabilization of USB -C connection.

Dropped Features:

N/A

Bugs Fixed:

ID	Fixed Bug Description
2071	Detected buttons click is longer than standard.
1886	Proper ethernet extension post-reset.
2069	Stability of USB device connection.

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Known Limitations (including compatibility limitations):

ID	Description
85605	Macbook Pro improper USB-C LAN connection. MacOS fix: Update Ventura/Sonoma MacOS Asix apple driver. https://www.asix.com.tw/en/product/USBEthernet/High-Speed_USB_Ethernet/AX88772C

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SWT3-41-U-T

Current Version:

Type	Number	Date
Firmware	V1.0.64879	November 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: November 30, 2023

Reference:

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U-T	N/A	N/A	N/A

Summary:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Replaced Products:

- N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SWT3-41-U-T

Current Version:

Type	Number	Date
Firmware	V1.0.64879	November 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: November 30, 2023

Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-41-U-T

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.
	Detected buttons click is longer than standard.
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.

Known Limitations (including compatibility limitations): N/A

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com