

Release Notes

Product Name:	WP-DEC7		
Current Version:	Туре	Number	Date
	Firmware	1.0.16	April 2024
	Software	-	_
	Web	–	-
	Hardware	-	-
RN Date:	April 1, 2024		
Reference:	19043		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-DEC7	Any	Yes	Yes

Summary:

- Fixed bugs.
- Added feature(s).

Codependency with Other Products and Software:

Product Name	Comments

• There is no codependency with other products or software.





Release Notes

Product Name:	WP-DEC7		
Current Version:	Туре	Number	Date
	Firmware	1.0.16	April 2024
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	April 1, 2024		
Reference:	19043		

New Features:

ID	New Feature Description	
GB-821	Added new Kramer Web-UI elements including new logo, address, splash image etc.	
	Added feature change AES128 encryption key.	
	Added a feature to deactivate the OSD completely configuration.	
GB-1053	Added the option to lower the Baud rate to 1200 and 2400.	
	Added the option to change the Multicast IP prefix.	
	Added daylight saving time with start/end date range configuration.	
	Added sleep image on/off configuration.	
	Added overlay timeout configuration.	
	Added 802.1X support on Service Port.	
	Added 802.1X status on Web-UI.	
	Added output resolution on decoder with Based in EDID.	

Modifications:

ID	Modification Description	
	Changed the CEC control on Web-UI with dropdown and SEND button.	

Dropped Features:

	Dropped Feature Description	





Release Notes

Bugs Fixed:

ID	Fixed Bug Description
GB-1033	#KDS-AUD command is relevant for ENC only - need to update API doc.
GB-1032	#X-AUD-DESC? command doesn't function as expected.
GB-896	Faulty response to front panel buttons - Response to button press is delayed.
GB-894	Sometimes switching time with same input resolution takes up to 7 sec.
GB-893	Slow response to front panel buttons, channel number returns after 2 seconds.
GB-1122	Request for a video MUTE and video UNMUTE command that can be sent through port 5000.
GB-1099	Pink line is shown on the display when using scale output mode of KDS- DEC7 (whether 1080P or 2160P) mode.
GB-847	The list returned by #SIGNALS-LIST includes only the active input.
GB-809	Getting gateway messages by using GTW-MSG-NUM doesn't filter messages by dates and displays all messages.
GB-765	When setting Syslog to OFF, file status displays 'log is open'.

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-866	After powering up the unit, the LCD and WEB display work slowly during the first 2 minutes.
GB-857	Lock panel feature should be removed from WP-DEC7.
GB-855	X-MUTE (+ "Mute" on webpage) mutes both HDMI and analog regardless the parameter.

Known Limitations (including compatibility limitations):

ID	Limitation Description	
	None listed	

Preceding Version: 0.8.6





Product Name:	WP-DEC7		
Current Version:	Туре	Number	Date
	Firmware	0.8.6	June 2022
	Software	_	_
	Web	_	_
	Hardware	-	-
RN Date:	June 2022		
Reference:	60-000990		

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-DEC7	N/A	N/A	N/A

Summary:

• This is a release note for a new product.





Product Name:	KDS-SW2-EN7		
Current Version:	Туре	Number	Date
	Firmware	0.8.6	June 2022
	Software	-	_
	Web	-	-
	Hardware	-	-
RN Date:	June 2022		
Reference:	60-000990		

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/KDS-SW2-EN7

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-866	After powering up the unit, the LCD and WEB display work slowly during the first 2 minutes.
GB-847	The list returned by #SIGNALS-LIST includes only the active input.
GB-809	Getting gateway messages by using GTW-MSG-NUM doesn't filter messages by dates and displays all messages.
GB-821	Need to update the new Kramer address in the About page.
GB-765	When setting Syslog to OFF, file status displays 'log is open'.

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

Preceding Version: N/A





WP-DEC7		
Туре	Number	Date
Firmware	0.11.12	January 2023
Software	-	-
Web	-	-
Hardware	-	-
January 31, 2023		
18696		
	TypeFirmwareSoftwareWebHardwareJanuary 31, 2023	TypeNumberFirmware0.11.12Software-Web-Hardware-January 31, 2023

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-DEC7	N/A	N/A	N/A

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name: Current Version:

WP-SW2-EN7 Number Date Туре Firmware 0.11.12 January 2023 Software _ _ Web _ _ Hardware _ _

RN Date: Reference: January 31, 2023 18696

Bugs to Fix in Future Versions:

Deferred Bug Description
None listed

Known Limitations (including compatibility limitations):

Limitation Description
None listed

Preceding Version: 0.8.6





Product Name:	WP-DEC7	WP-DEC7		
Current Version:	Туре	Number	Date	
	Firmware	0.11.12	January 2023	
	Software	_	_	
	Web	-	-	
	Hardware	-	-	
RN Date:	January 31, 2023			
Reference:	18696			

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-DEC7	N/A	N/A	N/A

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name:	WP-DEC7		
Current Version:	Туре	Number	Date
	Firmware	0.11.12	January 2023
	Software	-	-
	Web	-	-
	Hardware	-	-
RN Date:	January 31, 2023		
Reference:	18696		

Bugs to Fix in Future Versions:

Deferred Bug Description
None listed

Known Limitations (including compatibility limitations):

Limitation Description
None listed

Preceding Version: 0.8.6

