

Release Notes

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00 [107S 6.0.1 20200407.144349]	June 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 23, 2020

Reference: 016537

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KT-107S	Any	Yes	Yes

Technical Notes:

- Upgrading Kramer Control and Google Services.
- Includes Kramer Control Client App version 2.4.0.



Verify which Revision of KT-107S you are upgrading to ensure that you use the correct FW file. Using the wrong FW can cause the device to be unusable:

KT-107S Revision 01 or higher contains **R: 01** on the label on the rear of the unit and **R: 0104** or higher on the label on the box.

KT-107S Revision 00 does not contain an **R #** on the label on the rear of the unit and contains **R: 0003** or lower on the label on the box.

This firmware is applicable ONLY to KT-107S Revision 01 or higher.



KT-107S Revision 01 Unit Label



KT-107S Revision 01 Box Label



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Preceding Version: R1.00 [107S 6.0.1 20191111.144349]



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:	Type	Number	Date
	Firmware	R1.00 [107S 6.0.1 20191111.144349]	December 2019
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: December 15, 2019

Reference: 16034

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KT-107S	Any	Yes	Yes

Technical Notes:

- Upgrading Kramer Control and Google Services.
- Includes Kramer Control Client App version 2.2.9.



Verify which Revision of KT-107S you are upgrading to ensure that you use the correct FW file. Using the wrong FW can cause the device to be unusable:

KT-107S Revision 01 contains **R: 01** on the label on the rear of the unit and **R: 0104** or higher on the label on the box.

KT-107S Revision 00 does not contain an **R #** on the label on the rear of the unit and contains **R: 003** or lower on the label on the box.



KT-107S Revision 01 Unit Label



KT-107S Revision 01 Box Label

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00 [107S 6.0.1 20191111.144349]	December 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 15, 2019

Reference: 16034

The following changes were made in this version:

Modifications:

QC ID	Modification Description
	Upgraded Kramer Control application to version 2.2.9.
	Updated Google Services.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11102	PC recognizes USB-connected unit as rk3288 instead of KT-107S_Touch_Panel
11120	KT-107S Settings Menu shows wrong HW model

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: R1.00 [107S 6.0.1 20190226.114349]



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00 [107S 6.0.1 20190226.114349]	April 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 2019

Reference: 15221

Kramer Product Affected:

Product Name	Rev	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KT-107S	00	Any	Yes	Yes
KT-107S	01	Any	Yes	NA

Technical Notes:

- Includes Kramer Control Client App version 2.0.5.
- Updated Google services and Google Chrome.



Verify which Revision of KT-107S you are upgrading to ensure that you use the correct FW file. Using the wrong FW can cause the device to be unusable:

KT-107S Revision 01 contains **R: 01** on the label on the rear of the unit and **R: 0104** or higher on the label on the box.

KT-107S Revision 00 does not contain an **R #** on the label on the rear of the unit and contains **R: 003** or lower on the label on the box.



KT-107S Revision 01 Unit Label



KT-107S Revision 01 Box Label

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00 [107S 6.0.1 20190226.114349]	April 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 2019

Reference: 15221

The following changes were made in this version:

Modifications:

QC ID	Modification Description
	Includes Kramer Control version 2.0.5
	Updated Google services and Google Chrome.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11102	PC recognizes USB-connected unit as rk3288 instead of KT-107S_Touch_Panel
11120	KT-107S Settings Menu shows wrong HW model

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version:

R1.00,
Build 107S 6.0.1 20170425.112123



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00, Build 107S 6.0.1 20170425.112123	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2017

Reference:

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KT-107S	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-107S

Current Version:

Type	Number	Date
Firmware	R1.00, Build 107S 6.0.1 20170425.112123	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2017

Reference:

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/KT-107S>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11102	PC recognizes USB-connected unit as rk3288 instead of KT-107S_Touch_Panel
11120	KT-107S Settings Menu shows wrong HW model

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com