

## Release Notes

**Product Name:** RC-712M

**Current Version:**

Type	Number	Date
Firmware	4.0.45.49251	August 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** August 2018

**Reference:** 14385

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-712M	Any	Yes	Yes

### Technical Notes:

- Added support for Kramer Control.
- Bug fixes.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** RC-712M

**Current Version:**

Type	Number	Date
Firmware	4.0.45.49251	August 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** August 2018

**Reference:** 14385

The following changes were made in this version:

### New Features:

	New Feature Description
	Added support for Kramer Control.

### Bugs Fixed:

QC ID	Fixed Bug Description
1063	Query fail trigger (Comm_Err), behavior is inconsistent when defined in Ethernet ports

### Bugs to Fix in Future Versions:s

QC ID	Deferred Bug Description
	None listed.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** 4.0.43.42085



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** RC-712M

**Current Version:**

Type	Number	Date
Firmware	4.0.43.42085	December 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** December 2017

**Reference:** 12592

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-712M	Any	Yes	N/A

### Codedependency with Other Products and Software:

- There is no codedependency with other products or software.
- The following changes were made in this version:

### Modifications:

QC ID	Modification Description
	Removed unused command descriptions from the Help

### Bugs Fixed:

QC ID	Fixed Bug Description
1063	Query fail trigger (Comm_Err), behavior is inconsistent when defined in Ethernet ports
10772	The press event doesn't work when using Press-Release Functionality.

**Preceding Version:** F – 4.0.33.29083



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** RC-712M

**Current Version:**

Type	Number	Date
Firmware	4.0.33.29083	August 2016
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 2016

**Reference:** 11007

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-712M	Any	Yes	N/A

**Technical Notes:**

- Support for new flash component.
- Improved PJLINK protocol handling.

**Codependency with Other Products and Software:**

There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** RC-712M

**Current Version:**

Type	Number	Date
Firmware	4.0.33.29083	August 2016
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 2016

**Reference:** 11007

The following changes were made in this version:

### New Features:

	Description
	Support for new flash component
	Improved PJLINK protocol handling

### Bugs to be Fixed in Future Version:

QC ID	Description
1063	Query fail trigger (Comm_Err), behavior is inconsistent when defined in Ethernet ports

**Preceding Version:** F – 4.0.29.24637

**Product Name:** RC-712M

**Current Version:** F – 4.0.29.24637

**Version Date:** February 2016

**Reference:** 10063

The following changes were made in this version:

### Modifications:

- Support for K-Config 3 features.

### Known Issues:

- There are no known issues.

**Preceding Version:** F – 4.0.15.11355

**Product Name:** RC-712M



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Preceding Version:** F – 4.0.15.11355

**Version Date:** January 2014

**Reference:** 6380

The following changes were made in this version:

### **Added Features:**

Added support for K-Config 2 new relevant features:

- K-Config 2 – Support for new query mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports "Test command"
- K-Config 2 – Supports 10 Ethernet clients

### **Fixes:**

- Various bugs were fixed and performance stabilized.

### **Modifications:**

- Speed enhancements were made.

### **Known Issues:**

- There are no known issues.

**Preceding Version:** F – 4.0.11.9835



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)