

Pro	duct	Name:	SID-X2N
ro	auct	name:	SID-XZIV

Current Version:F - 8.5.21513Version Date:August 2015

Reference: 9199

Release Type:

⊠ Firmware	Software	Hardware	New Product
------------	----------	----------	-------------

Technical Notes:

- DisplayPort performance was improved.
- Spikes in the output signal were fixed.
- An HDBT outputted voltage problem was fixed.

Codependency with Other Products and Software:

• There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com



Current Version:F - 8.5.21513Version Date:August 2015

Reference: 9199

Fixes:

- DisplayPort input performance was improved.
- Spikes in the outputted signal after disconnecting the VGA input were fixed.
- Turning off 5V in the HDBT output when there was no input signal was fixed.

Known Issues:

- Poor image quality with 480p on VGA.
- Noises on analog audio output after auto switching from VGA to HDMI.

Preceding Version: F - 8.4.18473



KRAMER ELECTRONICS, Ltd.



Preceding Version: F - 8.4.18473

Version Date: April 2015

Reference: 8308

New Features:

- VGA signal timing is now extracted from the EDID.
- VGA phase adjustment was added.
- Only inputs with an active signal can be selected using front panel button.
- 5V cut out is now selectable by DIP-switch.

Known Issues:

- Poor image quality with 480p on VGA.
- Noises on analog audio output after auto switching from VGA to HDMI.
- Image quality issues on DP input when color space is YUV422.

Preceding Version: F - 1.30.90 (Valens)



KRAMER ELECTRONICS, Ltd.



Preceding Version: F – 1.30.90 (Valens)

Version Date: December 2014

Reference: 7920

Fixes:

• When the transmitter and receiver were powered up together, the monitor did not always receive video.

Known Issues:

• There are no known issues.

Preceding Version: F - 7.9.15670



KRAMER ELECTRONICS, Ltd.



Preceding Version: F - 7.9.15670 **Version Date:** August 2014

Reference: 7699

Fixes:

• VGA EDID was not written correctly.

• Removing and reconnecting VGA at 1080p resulted in no picture.

Known Issues:

There are no known issues.

Preceding Version: NP - 1.0



KRAMER ELECTRONICS, Ltd.



Product Name: SID-X2N **Preceding Version**: NP - 1.0

Version Date: March 2014

Reference: 1610

This is a release note for a new product.

Known Issues:

• There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.