

Release Notes

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.47.53564	June 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 25, 2019

Reference: 15397-B

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SL-10	Any	Yes	Yes

Technical Notes:

- Fixed a bug.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.47.53564	June 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 25, 2019

Reference: 15397-B

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed an issued that slowed down the device.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9231	Problem with disconnecting/connecting the device

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 4.0.45.49251



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	August 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2018

Reference: 14393

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SL-10	Any	Yes	Yes

Technical Notes:

- Added support for Kramer Control for relay and GPI/O.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	August 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2018

Reference: 14393

The following changes were made in this version:

New Features:

	New Feature Description
	Added support for Kramer Control for relay and GPI/O.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9231	Problem with disconnecting/connecting the device

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 4.0.43.42085



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.43.42085	December 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2017

Reference: 12588

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SL-10	Any	Yes	N/A

Codependency with Other Products and Software:

- There is no codependency with other products or software.

The following changes were made in this version:

Modifications:

QC ID	Modification Description
	Removed unused command descriptions from the Help

Bugs Fixed:

QC ID	Fixed Bug Description
10772	The press event doesn't work when using Press-Release Functionality.

Bugs to be Fixed in Future Version:

QC ID	Description
9231	Problem with disconnecting/connecting the device

Preceding Version: F – 4.0.33.29083



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.33.29083	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 11007

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SL-10	Any	Yes	N/A

Technical Notes:

- New flash memory support. PJLINK protocol handling improved.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Current Version:

Type	Number	Date
Firmware	4.0.33.29083	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 11007

The following changes were made in this version:

New Features:

	Description
	New flash memory support

Modifications:

QC ID	Description
	PJLINK protocol handling improved

Bugs to be Fixed in Future Version:

QC ID	Description
9231	Problem with disconnecting/connecting the device

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: F – 4.0.29.24637



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Preceding Version: F – 4.0.29.24637

Version Date: February 2016

Reference: 10064

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

Known Issues:

- There are no known issues.

Preceding Version: F – 4.0.15.11355



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: SL-10

Preceding Version: F – 4.0.15.11355

Version Date: March 2014

Reference: 6382

The following changes were made in this version:

Added Features:

- K-Touch – Support was added
- K-Config 2 – Support for new queries mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports "Test command"
- K-Config 2 – Support 10 Ethernet clients

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com