

Release Notes

Product Name: TP-580CT

Current Version:

Type	Number	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 28, 2021

Reference: 08391

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-580CT	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: TP-580CT

Current Version:

Type	Number	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 28, 2021

Reference: 08391

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/TP-580CT

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
19450	Display flickering may happen when CEC is enabled on some TV models. Workaround: Disable CEC on TV
19460	Rarely, display failure may occur post power-up with specific source types due to EDID read failure. Workaround: Replug source or HDBT link.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com