



Product Name: TP-588D
Current Version: FW – 1.31.00
Version Date: December 2015
Reference: 9363

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-588D	Any	Yes	N/A

Technical Notes:

- A missing video problem was fixed.
- This upgrade can be done only in the Kramer office. Please contact your Kramer dealer for details.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: TP-588D
Current Version: FW – 1.31.00
Version Date: December 2015
Reference: 9363

The following changes were made in this version:

Fixes:

- On some screens, video is missing with certain resolutions (for example, XGA on some Dell monitors).

Known Issues:

- When both DVI and HDMI outputs are connected and the user disconnects HDMI Out, there might be short video flickering on the DVI output.
- There might be audio loss on the DVI output with some displays.

Preceding Version: NP – 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: TP-588D
Current Version: NP – 1.0
Version Date: October 2015
Reference: N/A

This is a release note for a new product.

Known Issues:

- When both DVI and HDMI outputs are connected and the user disconnects HDMI Out, there might be short video flickering on the DVI output.
- There might be audio loss on the DVI output with some displays.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com