

Release Notes

Product Name: TP-600TRxr

Current Version:

Type	Number	Date
Firmware	5_0_175	August 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 24, 2021

Reference: 08428

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-600TRxr	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: TP-600TRxr

Current Version:

Type	Number	Date
Firmware	5_0_175	August 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 24, 2021

Reference: 08428

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/TP-600TRxr

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19582	Ethernet extension supported between GE-capable HDBT 3.0 extenders only, and not with 100M-capable HDBT extenders.
19583	For some source and sink models, HDCP-content initial display may get delayed due to source-sink HDCP hand-shake attempts.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com