



Product Name: VIA Campus
Current Version: F – 1.8.0116.644
Version Date: February 2016
Reference: 10051

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VIA Campus	1.8.1215.642	Yes	N/A
VIA Campus Bundle	1.8.1215.642	Yes	N/A

Technical Notes:

- DHCP and boot loops were fixed.
- A dual display issue was fixed

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VIA Campus
Current Version: F – 1.8.0116.644
Version Date: February 2016
Reference: 10051

The following changes were made in this version:

Fixes:

- Looping in DHCP mode when using FW version 1.8 with the patch was fixed.
- A boot-loop sequence problem was fixed.
- A dual display issue was fixed.

Known Issues:

- There are no known issues.

Preceding Version: NP – 1.0, F – 1.8.1215.643



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VIA Campus
Preceding Version: NP – 1.0, F – 1.8.1215.643
Version Date: January 2016
Reference: 9877

This is a release note for a new product.
The following changes were made in this version:

Fixes:

- A bug in streaming input was fixed.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com